

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

November 5, 1982


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-72. This report concerns T.S.3.7.6, "Two independent control area ventilation systems shall be operable". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

PBN:jfw  
Attachment

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. P. R. Bemis  
Senior Resident Inspector-NRC  
McGuire Nuclear Station

NOV 15 10:30  
NRC REGIONAL  
ATLANTA OFFICE

OFFICIAL COPY  
IE 22

8211170268 821105  
PDR ADOCK 05000369  
S PDR