Attachment to AECM-82/546

	Page 1 of 1
	EONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	M S G G S 1 2 0 0 - 0 0 0 0 0 0 0
ON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 1 0 1 4 8 2 8 1 1 1 1 2 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	On October 14, 1982, with no fire or smoke present, smoke detection zones 1-11
0 3	(133 ft. elev. Control Building HVAC Room) and 2-01 (SSW Pump House) alarmed and would
0 4	not reset. The zones were deactivated on the Fire Security Computer and a fire watch
0 5	established in accordance with T.S.3.3.7.9. This had no effect on the health and
0 6	safety of the public and did not constitute a threat to plant safety. This is being
0 7	reported pursuant to T.S.6.9.1.13.b.
08	
7 8	SYSTEM CAUSE CODE SUBCODE SUSCESSION SUBCODE SUBCODE SUSCESSION SUBCODE SUBCODE SUSCESSION SUSCESSION SUBCODE SUSCESSION SUBCODE SUSCESSION SUBCODE SUSCESSION SUBCODE SUSCESSION SUBCODE SUSCESSION SUSCESSION SUBCODE SUSCESSION SUBCODE SUSCESSION
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE COMPONENT NORTH ON PLANT SHUTDOWN HOURS 22 ATTACKMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 N 23 N 24 A 25 H 2 6 0 26 33 34 35 36 37 40 41 31 42 43 43 44 47 47 47 47 47
1101	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The alarms were caused by dust accumulation on detector N511H (zone 1-11) and
111	detector N582A (zone 2-01). Detector N511H was cleaned and returned to service on
1 2	October 15, 1982. Detector N582A was cleaned and returned to service on October 20,
1 3	1982. This is submitted as a final report.
1 4	
7 8	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 A 31 Audio and Visual Alarm
	9 10 12 13 44 45 46 80 CTIVITY CONTENT AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8	Z 33 Z 34 NA
1 7	NUMBER TYPE DESCRIPTION (39) NA NA
1 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) 8211170,119 8211112
1 9	TYPE DESCRIPTION (43) NA PDR ADUCK 05000416 PDR S
	PUBLICITY ISSUED DESCRIPTION 45
7 8	NA NA 68 69 80 5
	NAME OF PREPARER Original signed by Ron Byrd PHONE: