

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION
P.O. BOX 128
SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY
STATION MANAGER

RECEIVED
NRC

SCE

1982 NOV -1 AM 11:13

REGION V IRE TELEPHONE
(714) 492-7700

Nov 1, 1982

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-206
14-Day Follow-Up Report
Licensee Event Report 82-025
San Onofre Nuclear Generating Station, Unit 1

Reference: Letter, H. B. Ray (SCE) to R. H. Engelken (NRC),
24-Hour Confirmation Letter, LER 82-025,
dated October 14, 1982

The reference furnished written confirmation of a prompt report involving two instances of failure to provide fire watch coverage. This interim submittal is provided pending the issuance of a complete report on this matter. Licensee Event Report (LER) 82-025 is attached.

On October 20, 1982, a lapse of fire watch coverage took place similar to the incidents reported in the reference. Consequently, SCE finds it necessary to review the corrective action implemented as a result of the previous occurrences to determine whether or not additional corrective measures are required.

IE22

8211190118 821101
PDR ADOCK 05000206
S PDR

82-419

Mr. R. H. Engelken

- 2 -

A complete report of this matter, including a revised LER 82-025, will be furnished by November 10, 1982.

Sincerely,



Enclosure: Licensee Event Report No. 82-025

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission
Office of Management Information and Program Control

Institute of Nuclear Power Operations

L. Miller, (USNRC Resident Inspector, San Onofre Unit 1)