JUDIDE B JAN 1 5 1981 Syncor Corporation License No. 34-19008-01MD ATTN: Steven Shipper Docket No. 030-15203 Manager 2719 Manchester Road Akron, OH 44319 Gentlemen: This refers to the routine safety inspection conducted by Messrs, D. R. Gibbons and W. H. Schultz of this office on December 18 and 20, 1990 of activities authorized by NRC Byproduct Material License No. 34-19008-01MD and to the discussion of our findings with you at the conclusion of the inspection. The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records. observations, independent measurements, and interviews with personnel. During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required. In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room. The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511. We will gladly discuss any questions you have _oncerning this inspection. Sincerely, William H. Schultz, Chief Nuclear Materials Safety Section 1 Enclosure: Notice of Violation uc w/enclosure: Frank Comer, Corporate Radiation Safety Officer JE07 DCD/DCB (RIDS) RIII RIII was you WWS Gibbons/da Schultz 1-15-91 1-15-91 9101240119 910115 REG3 LIC30 34-19008-01MD PDR