January 18, 1991



CERTIFIED MAIL RETURN RECEPT REQUESTED

Mr. William L. Kregloe Virginia Water Control Board Valley Regional Office 116 North Main Street P. O. Box 268 Bridgewater, Virginia 22812

Re: Oil spill at North Anna Power Station

Dear Mr. Kregloe:

This letter confirms our report by telephone of an oil spill that occurred on January 16, 1991 at North Anna Power Station. Mr. John Hart in the Valley Regional Office was notified of the spill at 1615 hours on the 16th.

Station personnel were moving drums of waste diesel fuel from within station security to a remote collection area. The closed drums had been loaded on a flatbed truck for transport when heavy outsides of the drums and into a nearby storm drain which discharges to the discharge canal via Outfall 004. A total of much less than one gallon of oil reached the canal.

Upon discovery, absorbant pads were placed around the truck and in the path of the runoff to the stormdrain. The light sheen of oil on the water's surface was contained by a permanent boom around materials. Personnel within the boom was removed by absorbant discharge canal.

Awareness of how such an incident can cause a discharge of cil is the best source for prevention of reoccurrence. Personnel were admonished to take greater care not to leave oil on the outside of to stormdrains.

No apparent environmental damage was caused by the oil spilled. No oil was deposited on the shoreline nor were fish or

JE23 10

Mr. William L. Kregloe Page 2 January 18, 1991

wildlife affected. If you have any questions regarding this incident, please contact this office.

Sincerely,

B. M. Marshall, P.E.

Manager

Water Quality

CC: U. S. NRC
Docket No. 50-338/50-339
101 Marietta St., NW
Suite 2900
Atlanta, GA 30323

U. S. NRC Attn: Docket Control Desk Docket No. 50-338/50-339 Washington, DC 20555

NRC Seh or Resident Inspector Docket No. 50-338/50-339 North Anna Power Station