TENNESSEE VALLEY AUTHORITY

CHATTANOOGA TENNESSEE 37401 1750 Chestnut Street Tower II

November 17, 1982

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE REPORT SQR0-50-328/821.2

The enclosed report provides details concerning the inoperability of one pressurizer pressure channel. This report is submitted in accordance with Sequoyah unit 2 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

irector of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, Sequoyah

OFFICIAL COPY