

APPENDIX A

NOTICE OF VIOLATION

Woodward-Clyde Consultants
Wayne, New Jersey 07470

Docket No. 030-19211
License No. 29-19765-01

As a result of the inspection conducted on December 13, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1990), the following violations were identified:

Condition 21 of License No. 29-19765-01 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in an application dated February 18, 1987.

Item No. 3.3 of this application requires that radiation survey instruments be calibrated semi-annually.

Contrary to the above, on July 11, 1990, a radiation survey instrument, used at a jobsite, was not calibrated semi-annually. Specifically, survey instrument serial number 31612 used at Eglin AFB with a 50 millicurie cesium-137 source, had not been calibrated since October 11, 1989.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Woodward-Clyde Consultants is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY

ML DL WOODWARD - 0003.0.0
01/14/91

9101290017 910118
REG1 LIC30
29-19765-01 PDR

RETURN ORIGINAL TO
REGION I

IE:07