

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION V

1450 MARIA LANE, SUITE 210 WALNUT CREEK, CALIFORNIA 84596

JAN 0 9 1991

Docket Nos. 50-206, 50-361, 50-362

Southern California Edison Company Irvine Operations Center 23 Parker Street Irvine, California 92718

Attention: Mr. Harold B. Ray

Senior Vice President, Nuclear

Gentlemen:

This refers to the routine inspection conducted by Mr. Harold D. Chaney of this office on December 10-14, 1990, of the activities authorized by NRC license Nos. DPR-13, NPF-10, and NPF-15, and to the findings discussed with Mr. P. Knapp and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,

G. P. Guhas Gregory P. Juhas, Chief Reactor Radiological Protection Branch

Enclosure: Inspection Report Nos. 50-206/90-41, 50-361/90-41, 50-362/90-41

cc w/enclosure: D. J. Fogarty, Executive Vice President
H. E. Morgan, Vice President and Site Manager
R. L. Krieger, Jr., Acting Station Manager
State of California

9101290074 910109

bcc w/enclosure: Docket File Resident Inspector Project Inspector G. Cook B. Faulkenberry J. Martin

bcc w/o enclosure: M. Smith J. Zollicoffer

REGION V HDChaney 1/9/90

GPY uhas 1/9/901

PEOLEST COPY

PDR NO