

DCS

JAN 23 1991

Docket No. 030-14885

License No. 37-18253-01

Northeastern Hospital of Pennsylvania
2301 East Allegheny Avenue
Philadelphia, Pennsylvania 19134-4499

Gentlemen:

Subject: Inspection No. 030-14885/90-001

This refers to your letter dated October 3, 1990, in response to our September 20, 1990 inspection.

We are enclosing an amended copy of the NRC Form 591 issued to you at the conclusion of the inspection. Item H is amended to read 35.70; failure to perform weekly surveys for contamination and 35.205; failure to perform xenon trap monitoring as required.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

No reply to this letter is required. Your cooperation with us is appreciated.

Sincerely,

ORIGINAL SIGNED BY:
JEAN GRESICK-SCHUGSTA



Mohamed M. Shanbaky, Chief
Nuclear Materials Safety Section A
Division of Radiation Safety
and Safeguards

Enclosure:
Amended NRC Form 591

cc:
Public Document Room (PDR)
Nuclear Safety Information Center (NSIC)
Commonwealth of Pennsylvania

OFFICIAL RECORD COPY

RL NORTHEASTERN - 0001.0.0
01/08/91

9101290087 910123
REG1 LIC30
37-18253-01 PDR

RETURN ORIGINAL TO
REGION I

12-07

Northeastern Hospital of Pennsylvania 2

bcc:
Region I Docket Room (w/concurrences)

RI:DRSS
Darden/bj

RI:DRSS
Shanbaky

01/17/91

OFFICIAL RECORD COPY

RL NORTHEASTERN -- 0002.0.0
01/08/91