

Entergy Operations, Inc. P.O. Box B Killona LA 70060 Tel 504 739-6630

W3F1-91-0029 A4.05 QA

February 18, 1991

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Subject:

Waterford 3 SES Docket No. 50-382 License No. NPF-38

Waterford 3 Organization Change

Gentlemen:

Entergy Operations, Inc. has recently restructured the Waterford 3 site operations organization. This has necessitated a change to the Waterford 3 SES Emergency Plan.

Pursuant to 10CFR50, Appendix E, Section V, we are herewith informing you of the resulting changes that will be required to the Emergency Plan. These changes do not decrease the effectiveness of the Emergency Plan based on a 10CFR50.54(q) review.

Attached is a copy of the restructured Waterford 3 Site Organization Chart which at a minimum will require changes to Section 5.1.1, Figure 5-1A of the Emergency Plan and Section 13.1 of the Final Safety Analysis Report (FSAR).

These changes will be incorporated into the next revisions of the Emergency Plan and the FSAR which are scheduled for issuance during the fourth quarter of 1991.

hould you have any questions, please feel free to contact me.

Very truly yours,

R.F. Burski

Director, Nuclear Safety

RFB/TWG/ssf Attachment

Mitachment

cc: Messrs. R.D. Martin, NRC Region IV

D.B. Spitzberg, NRC Region IV

W.M. McNeill, NRC Region IV

D.L. Wigginton, NRC-NRR

E.L. Blake

R.B. McGehee

NRC Resident Inspectors Office

Mo06