



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

November 22, 1982

JAMES P. MCGAUGHY, JR.  
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 3100  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Smoke Detector Alarmed and  
Would Not Reset  
Reference: LER 82-101/03 L-0  
AECM-82/560

On October 22, 1982, the smoke detectors in the zone covering the Auxiliary Building west corridor area, elevation 185 feet, alarmed and would not reset. This event is being reported pursuant to T.S.3.3.7.9. Attached is LER 82-101/03 L-0.

Yours truly,

JPM:sap  
Attachment

- cc: Mr. N. L. Stampley (w/a)
- Mr. R. B. McGehee (w/c)
- Mr. T. B. Conner (w/o)
- Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk (w/a)  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

OFFICIAL COPY  
IE 22

NOV 23 10:51  
REGIONAL OFFICE  
ATLANTA, GEORGIA