

DSS

FEB 12 1991

Docket No. 030-19223

License No. 20-19778-01

ABC Testing, Incorporated  
ATTN: Carelton A. Richardson  
President  
95 First Street  
Bridgewater, Massachusetts 02324

Gentlemen:

Subject: Inspection No. 030-19223/90-01

This refers to your letter dated January 15, 1991, in response to our letter dated December 28, 1990.

We have no disagreement with Para 11.6.2. of your Operating and Emergency Manual. However, it is the requirement of the regulation 10 CFR 20.105(b)(1), that the licensee's use of radioactive materials shall not result in an unrestricted area exceeding a dose of 2 millirem in any one hour, at any time. We acknowledge that when your radiographer became aware of this situation he took corrective actions. However, the radiographer should have established the expected restricted area prior to exposing the source.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:  
Paul D. Swetland

*for*  
John R. White, Chief  
Nuclear Materials Safety Section C  
Division of Radiation Safety  
and Safeguards

cc:  
Public Document Room (PDR)  
Nuclear Safety Information Center (NSIC)  
Commonwealth of Massachusetts

9102270105 910212  
REG1 LIC30  
20-19778-01 PDR

OFFICIAL RECORD COPY

RL ABC - 0001.0.0  
02/06/91


0300030  
Return Original to Region I

IE:07/ |


*LF07*

bcc:  
Region I Docket Room (w/concurrences)

RI:DRSS  
Thompson/bj

  
RI:DRSS  
White

01/ /91

 91

OFFICIAL RECORD COPY

RL ABC - 0002.0.0  
02/06/91