



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
Region 1  
475 Allendale Rd.  
King of Prussia, Pennsylvania 19406

Southwood Community Hospital  
License # 20-20554-01  
Docket # 030-19406  
Jan. 9, 1991

Re: Inspection by Lester M. Tripp... Nov. 8, 1990  
**Routine Inspection #030-19406\90-001**  
NRC Letter dated 1-3-91

The Severity level IV violation, 10CFR 35.315(a)(7) has been corrected as of Jan 9, 1991. Rooms with private sanitary facilities assigned to patients (10CFR35.75) who receive radiopharmaceutical therapy are surveyed for removable contamination prior to assigning other patients to the rooms. The in-house physicist W. Vorotnitsky incorporated the survey in writing into the standard routine for radiopharmaceutical therapy procedures. The documentation of each survey will assure future compliance with this regulation.

  
-----  
Dr. George F. Edeburn  
Radiation Safety Officer

  
-----  
John Dalton  
Administrator


9102270169 910211  
REG1 LIC30  
20-20554-01 PDR

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
Region 1  
475 Allendale Rd.  
King of Prussia, Pennsylvania 19406.


Southwood Community Hospital  
License #20-20554-01  
Docket #030-19406  
Jan. 9, 1991

Re: Inspection by **Lester M. Tripp**...Nov. 8, 1990  
**Routine Inspection #030-19406\90-001**  
NRC Letter dated 1-3-91

The Severity level IV violation, 10CFR 35.315(a)(7) has been corrected as of Jan 9, 1991. Rooms with private sanitary facilities assigned to patients (10CFR 35.75) who receive radiopharmaceutical therapy are surveyed for removable contamination prior to assigning other patients to the rooms. The in-house physicist W. Vorotnitsky incorporated the survey in writing into the standard routine for radiopharmaceutical therapy procedures. The documentation of each survey will assure future compliance with this regulation.



Dr. George F. Edeburn  
Radiation Safety Officer



John Dalton  
Administrator