MAL FURM JUL (7.77) LICENSEE EVENT REPORT CONTROL BLOCK: 10) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) DO O O O O - 0 0 3 4 1 1 1 1 4 26 LICENSE TYPE 30 CON'T REPORT 1 1 1 0 2 4 8 2 8 1 1 1 1 0 8 2 9 68 69 EVENT DATE 74 75 REPORT DATE 80 0 1 LO 0 0 0 0 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On October 24, 1982, during routine surveillance on the 130' Elevation Containment Air 0 2 Lock, an operator observed excessive leakage on the inner door seals. The door was 0 3 repaired and satisfactorily vested. On October 26, 1982, during similar surveillance, 0 4 seal leakage on the 100' Elevation Air Lock inner door was also found to be excessive. 0 5 In both cases, Action Statement 3.6.1.3.a was entered, and the outer door was 0 6 maintained closed. The events constituted operation in a degraded mode in accordance 0 7 with Technical Specification 6.9.1.9.b. SYSTEM CAUSE CAUSE COMP CODE CODE SUBCODE COMPONENT CODE SUBCODE X (13) T R 14 (12) A (15 0 9 18 SEQUENTIAL OCCURRENCE REVISION REPORT REPORT NO. CODE LER RO REPORT TYPE 8 2 9 13 NUMBER ACTION ACTION METHOD SUBMITTED NPRD-4 PRIME COMP. COMPONENT HOURS (22) FORM SUB. SUPPLIER MANUFACTURER N 24 Z (21) 0 0 0 0 Y 23 A (19 25 (26) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) In both cases, improper operation of the air lock doors by station personnel resulted 10 in excessive leakage. The air locks were repaired and the action statement terminated, 1 1 The problem is presently being addressed by a number of corrective measures; final 1 2 evaluation is pending completion of the measures. 1 3 1 4 METHOD OF FACILITY STATUS OTHER STATUS (30) \* POWER DISCOVERY DESCRIPTION (32) 8 (28) NA B (31 Surveillance Testing CONTENT AMOUNT OF ACTIVITY (35 RELEASED OF RELEASE LOCATION OF RELEASE (36) 33 Z 34 6 Z NA NA 10 11 80 PERSONNEL EXPOSURES NUMBER DESCRIPTION Z (38) 0 PERSONNEL INJURIES 80 DESCRIPTION (41 8 8211290565 821110 LOSS OF OR DAMAGE TO FACILITY 43 80 PDR ADOCK 05000311 DESCRIPTION PDR 9 Z (42) NA 10 PUBLICITY NRC USE ONLY DESCRIPTION 45 (44) 2 0 NA 68 69 R. Frahm 609/935-6000 EXT 3078 NAME OF PREPARER . PHONE .