

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205 November 23, 1982

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-13 File 0260/L-835.0 Inoperable Fire Rated Seals-Follow-up Report LER 82-041/99 X-1 AECM-82/567

On August 8, 1982, three four-inch penetrations were found not sealed. These penetrations are located between rooms 1D302, 1D303, and 1D304. This report is being submitted pursuant to Technical Specification 3.7.7, and as a follow-up to LER 82-041/03 L-0, dated September 7, 1982. Attached is LER 82-041/99 X-1.

FOR J. S. Meborghy JK.

JPM: sap Attachment

cc: Mr. N. L. Stampley (w/a) Mr. R. B. McGehee (w/o) Mr. T. B. Conner (w/o) Mr. G. B. Taylor (w/o)

> Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

OFFICIAL COPY

8211290583 821123 PDR ADOCK 05000416 PDR S

Member Middle South Utilities System