

B2112990598 B21102
PDR ADOCK 05000293
PDR

DESIGNATED ORIGINAL

Certified By

map

BOSTON EDISON COMPANY
PROMPT REPORTABLE OCCURRENCE
TELECOPY MESSAGE

TO: (215) 337-5324
Telephone Number

DATE/TIME: Nov. 2, 1992

TO: Ronald C. Haynes
Regional Administrator, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

FROM: Pilgrim Nuclear Power Sta.
RND#1, Rocky Hill Road
Plymouth, MA 02360

Docket Number 50-293
License DFR-35

Assigned LER Number 82-049/01X-0

Reported per T.S. Section 6.9.8.1.f.

Event Description: On 11/2/82, it was found that the "A" Safety Valve had been set with nitrogen at the steam relief setting (1240 psig). This setting could have allowed relief approximately 80 psig above the T.S. limit. A plant shutdown is currently underway.

Cause and Corrective Action: Personnel error is the cause of this event. A properly tested spare valve will be installed. Personnel have been admonished to read and follow procedures exactly. Procedure changes may be necessary to prevent recurrence.

Facility Status:

- c) Routine Startup _____
- d) Routine Shutdown _____
- a) Steady State X
- f) Load Changing _____

- 100 % Thermal MW
- g) Shutdown _____
- h) Refueling _____
- i) Other _____
- j) Not Applicable _____

A written followup report will be sent within two weeks.

NRC Person Notified J. R. Johnson Prepared by G. G. Whitney

Mail (2) copies to:

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

cc: Standard LER Distribution

GM

1029