

November 19, 1982

Mr. J. G. Y Ppier, Regional Administrator Office of Inspection and Enforcement, Region III U. S. NUCLEAR REGULATORY COMMISSION 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

## DOCKET NO. 50-266 LICENSEE EVENT REPORT NO. 82-019/01T-0 POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report No. 82-019/01T-0 (a 14-day follow-up report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.3, "Abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment."

Very truly yours,

Executive Vice President

Sol Burstein

Enclosure

Copy to NRC Resident Inspector