Mr. Richard P. LaRhette Institute of Nuclear Power Operations 700 Galleria Parkway Atlanta, Georgia 30339-5957

Dear Mr. LaRhette:

Enclosed for your information is a list of generic communications under development by the NRC staff. The list includes those Generic Letters (GL), Admini trative Letters (AL), Bulletins (BL), and Information Notices (IN) report to us by December 1, 1993. New items on the list or changes in the stall of listed items are identified by a notation in brackets. Starting with this report, items are entered on the list by type and by date initiated.

Sincerely,

Original signed by
Gail H. Marcus, Chief
Generic Communications Branch
Division of Operating Reactor Support
Office of Nuclear Reactor Regulation

Enclosure: As stated

cc: S. D. Richardson, Defense Programs (Savannah River), DOE

R. W. Barber, Safety and Quality Assurance, DOE S. Scott, Office of Nuclear Safety, NS-10, DOE

DISTRIBUTION w/enclosure
JIbarra, OCM
JGuttmann, OCM
JCallan, NRR
All NRR Division Directors
All Regional Division Directors
CACarpenter, NRR
KRamsey, NMSS
LCShao, RFS
GHolahan, AEOD
PWBaranowsky, AEOD
KAbraham, RI
JStrasma, RIII
GCook, RV
OGCB Members

JScarborough, OCM
WHBateman, EDO
RIngram, NRR
All NRR Branch Chiefs
KGray, NRR
JTLarkins, ACRS
FCCombs, NMSS
WMinners, RES
JERosenthal, AEOD
FIngram, OPA
KClark, RII
JGilliland, RIV
Central Files
PDR
OGCB R/F

Document Name: INPOLIST.LTR

OGCB: DORS: NRR
JBirmingham
11/30/93 JLB

JBirmingham R/F

DORS R/F

C/OGCB:DORS:NRR GHMarcusGH7 11/30/93

NRG FILE CENTER COPY

090060

9312150187 931130 PDR OR9 EPSINPO PDR

PROPOSED GENERIC COMMUNICATIONS IN PREPARATION WITHIN THE NRC

DT NTRD TYPE	SUBJECT	SOURCE	CONTACT	PHONE NO
	ISI OF STEEL CONTAINMENTS, REFUEL CAVITIES & DRAINAGE SYSS	NRR DE ESGB		(301) 504-3315
01/08/91 GL	NRC POSITION ON EPRI OBE CRITERIA & EPRI GUIDE FOR EARTHQUAKES	NRR DE ECGB	Goutam Bagchi	(301) 504-2733
11/15/91 GL	INSERVICE LEAK AND HYDROSTATIC TESTING TS BACKFIT APPEAL	NRR DORS	Tom Dunning	(301) 504-1189
	REMOVAL OF TS TABLES FOR RESPONSE TIME LIMITS	NRR DORS	Tom Dunning	(301) 504-1189
09/02/92 GL	TECH SPEC MODIFICATIONS FOR EMERGENCY & SECURITY PLANS	NRR DORS	Tom Dunning	(301) 504-1189
	SOLUTIONS & ACTIONS FOR BWR THERMAL HYDRAULIC INSTABILITIES		Laurence E Phillips	(301) 504-3232
GL	[CANCELED] AVAILABILITY AND ADEQUACY OF DESIGN BASES INFORMATION			
01/04/93 GL	ANALOG TO DIGITAL INSTRUMENTATION PEPLACEMENTS UNDER 10 CFR 50.59 RULE	NRR DRCH HICB		(301) 504-2825
01/10/93 GL	GL 86-10 SUP, FIRE PROTECTION AND USE OF THERMOLAG	NRR DSSA SPLB	Pat Madden	(301) 504-2854
02/09/93 GL	GUIDANCE ON CORRECTIVE MEASURES IN MEDIUM ENERGY ASME PIPE	NRR DE EMCB	Don Kirkpatrick	(301) 504-1849
03/15/93 GL	GL 86-10 SUP, "IMPLEMENTATION OF FIRE PROTECTION REQUIREMENTS"	NRR DSSA SPLB	Pat Madden	(301) 504-8254
04/19/93 GL	MODEL TECH SPECS TO INCORPORATE THE REVISED 10 CFR PART 20		S P Klementowic z	(301) 504-1084
04/28/93 GL	[CANCELED IN FAVOR OF RULEMAKING] LOW-TEMPERATURE OVER PRESSURE SETPOINT METHODOLOGY	NRR PDIII-3	Daniel McDonald	(301) 504-1408
05/19/93 GL	LINE ITEM TS IMPROVEMENT, ACCELERATED EDG TESTING	NRR DORS OTSB	Om Chopra Tom Dunning	(301) 504-3150
06/16/93 GL	INTERFACING SYSTEMS LOCA IN LIGHT WATER REACTORS	RES RPSIB	Gary Burdick	(301) 492-3812

PROPOSED GENERIC COMMUNICATIONS IN PREPARATION WITHIN THE NRC

DT NTRD TYPE	SUBJECT	SOURCE	CONTACT	PHONE NO
	VOLUNTARY REPORTING OF ADDITIONAL RADIATION EXPOSURE DATA	RESEARCH	C Raddatz	(301) 504-1717
GL	GL 89-10 SUP, INACCURACY OF MOTOR-OPERATED VALVE DIAGNOSTIC EQUIPMENT		Tom Scarbrough	(301) 504-2794
09/08/92 IN	APPLICABILITY OF 10 CFR 70.24, "CRITICALITY ACCIDENTS"	NRR DRPW PD5	L Kokajko	(301) 504-1369
	IN 92-51 SUP: MISAPPLICATION AND INADEQUATE TESTING OF MCCBs	NRR RVIB DRIL	Steve Alexander	(301) 504-2995
12/07/92 IN	POTENTIAL FAILURES OF EDGs CAUSED BY COLD FUEL OIL	REGION I	Vern Hodge	(301) 504 1861
	NRC STUDY ON PRESSURE LOCKING & THERMAL BINDING OF GATE VALVES		Tom Scarbrough	
03/03/93 IN	TESTING OF BACKUP EMERGENCY RESPONSE FACILITIES	NRR DRSS PEPB	Edwin Fox	(301) 504-2908
	DEGRADATION OF SR SYSTEMS DURING VALVE STROKE SURVEILLANCE TESTING	REGION II	P Kim VanDoorn	(704) 875-1681
IN	[IN 93-87 ISSUED 11/4/93] FUSE PROBLEMS WITH WESTINGHOUSE 7300 PRINTED CIRCUIT CARDS	REGION II	T J Kim	(301) 504-2841
IN	TURBINE OVERSPEED AND RCS COOLDOWN DUE TO RELATCHING OF MAIN TURBINE	NRR DORS OEAB	Eric Benner	(301) 504-1171
	POTENTIAL CHARGING PUMP MALFUNCTIONS	NRR DSSA SRXB	Don Kirkpatrick	(301) 504-1849
05/21/93 IN	1E BUS AND LOAD VULNERABILITY TO UNEXPECTED BUS TRANSFER	NRR DE EELB		(301) 504-2778
05/21/93 IN	UNDERVOLTAGE RELAY SETTINGS	NRR DSSA EELB	Nancy Campbell	(301) 504-2836
IN	CERTIFYING OFFICIALS ON NRC FORM 313, "APPLICATION FOR MATERIAL LICENSE"	NMSS IMNS IMOB	Scott W Moore	
06/17/93 IN	COMMON DEPENDENCIES IN CCW SYSTEMS	REGION II	J L Shackelford	

PROPOSED GENERIC COMMUNICATIONS IN PREPARATION WITHIN THE NRC

DT NTRD TYPE	SUBJECT	SOURCE	CONTACT	PHONE NO
06/17/93 IN	POTENTIAL PROBLEMS WITH FIRE BARRIER PENETRATIONS	REGION I	Dick Kiessel	(301) 504-2840
	POTENTIAL FAILURE OF LONG-TERM N2 SUPPLY FOR ADS AT FITZPATRICK		David Shum	(301) 504-2860
	PROBLEMS IN PREDICTION OF TORQUE RQRMNTS FOR BUTTERFLY VALVES	REGION II	T J Kim	(301) 504-2841
07/21/93 IN	FAILURE OF WILCO FIRE HOSE NOZZLES	NRR DRIL RVIB	W Orders	(803) 383-4571
	DEGRADATION OF MEDIUM VOLTAGE CABLE IN UNDERGROUND APPLICATIONS	REGION V	Bill Ang	(510) 975-0310
IN	DEGRADATION OF OFFSITE POWER SOURCE FROM SALT BUILDUP ON INSULATORS	REGION II	R Schin	(404) 331-5561
07/29/93 IN	IN SUP: FALSIFICATION OF PLANT RECORDS	NRR DORS OEAB	Tom Greene	(301) 504-1175
07/29/93 IN	MELTED INSULATION ON RELAYS AT ST LUCIE	NRR DORS OEAB	Tom Koshy	(301) 504-1176
	MISAPPLICATION OF FUSES IN SAFETY RELATED SYSTEMS (STP)	NRR DORS OEAB	Nick Fields	(301) 504-1173
	POTENTIAL BREACH OF PRIMARY CONTAINMENT	NRR DORS OEAB	Tom Greene	(301) 504-1175
08/02/93 IN	LOSS IN SUBCOOLING MARGIN FOR NATURAL CIRC COOLDOWN FROM STUCK SRV	NRR DOAS OEAB	Phil Harrell	(817) 860-8250
08/05/93 IN	[CANCELED] STEAM GENERATOR TUBE LEAK DETECTION PROBLEMS AT PALO VERDE	NRR DORS EAB	Tom Koshy	(301) 504-1176
08/12/93 IN	EXERCISING CONTROL RODS TO MEET TECH SPEC INSERTION TIMES	NRR DORS EAB	Dave Skeen	(301) 504-1174
08/12/93 IN	IN 92-69 SUP, YARD WATER LEAKING THROUGH CONDUITS INTO BUILDINGS	NRR DORS EAB	Neal Hunemuller	(301) 504-1152
	GE MAGNA-BLAST BREAKER SPRING MISALIGNMENT	REGION V	Peter Wen	(301) 504-2832

Page No. 4 11/30/93

PROPOSED GENERIC COMMUNICATIONS IN PREPARATION WITHIN THE NRC

DT NTRD TYPE	SUBJECT	SOURCE	CONTACT	PHONE NO
09/20/93 IN	INADEQUATE RCS CONTROL DURING SHUTDOWN	NRR DORS OEAB	Eric Benner	(301) 504-1171
	RESULTS OF RECENT SWS OPERATIONAL PERFORMANCE INSPECTIONS	NRR DRIL RSIB	T J Kim	(301) 504-2841
09/20/93 IN	FAILURE OF EDGS TO START	NRR DRIL RVIB	Walter Haass	(301) 504-3219
09/28/93 IN	PROBLEMS DETECTING FAILURE OF ATWOOD MORRILL MSIVS TO CLOSE	REGION IV	Neal Hunemuller	(301) 504-1152
09/30/93 IN	MOTOR BRAKES ON MOTOR OP VALVES		Tom Scarbrough	
10/04/93 IN	INTEGRATED CIRCUIT SOCKET PERFORMANCE DEFICIENCIES	REGION III	Ed Schweibinz	(708) 790-5542
10/04/93 IN	FAILURE OF WESTINGHOUSE\ABB RELAY FROM INSULATION DEGRADATION	REGION II	T J Kim	(301) 504-2821
10/04/93 IN	CRACKING IN VALVE YOKES AT PEACE BOTTOM	REGION I	Cliff Anderson	(215) 337-5227
10/04/93 IN	IN 87-10 SUP, WATER HAMMER DURING RESTART OF RHR PUMPS	REGION III	Isa T Yin	(708) 790-5581
10/06/93 IN	MISADJUSTMENT OF 4160 VOLT GE MAGNE-BLAST BREAKERS	REGION III	Peter Wen	(301) 504-2832
10/06/93 IN	IN 93-66 REV, SWITCHOVER TO HOTLEG RECIRCULATION AFTER A LOCA	NRR DE EMCB	Nancy Campbell	(301) 504-2836
	STEAM GENERATOR TUBE RUFTURE AT MCGUIRE	NRR DE EMCB	Herb Conrad	(301) 504-2703
10/06/93 IN	OBSERVATIONS ON LESSONS LEARNED FROM HURRICANE ANDREW	NRR DE EGCB	Hans Ashar	(301) 504-2851
10/18/93 IN	IN 93-17 REV, SAFETY SYSTEMS RESPONSE TO LOCA AND LOOP		Jim Lazevnick	(301) 504-2782
IN	[IN 93-90, ISSUED 12/1/93] UNISOLATABLE REACTOR COOLANT SYSTEM LEAK FOLLOWING REPEATED APPLICATIONS OF LEAK SEALANT	NRR DORS OEAB	Eric Benner	(301) 504-1171
11/01/93 IN	[NEW] IN 89-77 SUP, DEBRIS IN CONTAINMENT SUMPS	REGION IV	Peter Wen	(301) 504-2832

PROPOSED GENERIC COMMUNICATIONS IN PREPARATION WITHIN THE NRC

DT NTRD TYPE	SUBJECT	SOURCE	CONTACT	PHONE NO
11/04/93 IN	[NEW] TURBINE BLADE FAILURES FROM TORSIONAL FORCES	NRR DE EMCB	John Tsao	(301) 504-2702
11/08/93 IN	[NEW] FAILURES OF TORQUE SWITCHES IN LIMITORQUE OPERATORS	REGION I	Tom Scarbrough	(301) 504-2794
11/08/93 IN	[NEW] PROBLEMS WITH WESTINGHOUSE NBFD RELAYS	REGION III	Marsha Gamberoni	(301) 504-3024
11/12/93 IN	[NEW] MITIGATION OF COMMON DEPENDENCIES IN CCW SYSTEM	REGION IV	Don Kirkpatrick	(301) 504-1849
11/12/93 IN	[NEW] FAILURE OF CONT SPRAY ISO VALVE TO OPEN	EMEB DE NRR	Don Kirkpatrick	(301) 504-1849
11/12/93 IN	[NEW] UNA"THORIZED FORCED ENTRY AT TMI	PSGB DRSS NRR	T. J. Kim	(301) 504-2841
11/15/93 IN	[IN 93-89, ISSUED 11/26/93] POTENTIAL PROBLEMS WITH BWR LEVEL INSTRUMENTATION BACKFILL MODIFICATIONS	SRXB DSSA NRR	Peter Wen	(301) 504-2832
11/17/93 IN	[NEW] REPORTING REQUIREMENTS FOR BANKRUPTCY	IMOB INMS	Kevin Ramsey	(301) 504-2534
11/18/93 IN	[IN 93-88, 11/30/93] STATUS OF MOTOR-OPERATED VALVE PERFORMANCE PREDICTION PROGRAM BY THE ELECTRIC POWER RESEARCH INSTITUTE	EMEB DE NRR	Tom Scarbrough	
11/29/93 IN	[NEW] MAIN TURBINE FIRE CAUSED BY OIL SOAKED INSULATION	REGION IV	Thomas Stetka	
IN	[NEW] PROBLEMS IN HANDLING OF FUEL ASSEMBLIES DUE TO MISOPERATION OF REFUELING EQUIPMENT	REGION I	E M Kelly	(215) 337-5183
11/30/93 IN	[NEW] BWR JET PUMP HOLD DOWN FAILURES	REGION IV	T J Kim	(301) 504-2841
IN	[NEW] ISSUES ASSOCIATED WITH USE OF STRONTIUM-89 AND OTHER BETA EMITTING RADIOPHARMACEUTICALS	NMSS IMNS IMAB	James A Smith	(301) 504-2613
08/11/93 AL	ACKNOWLEDGMENT OF RECEIPT OF DOCUMENTS FROM LICENSEES	NRR PMAS PMSB	Dick Kiessel	(301) 504-2840