fat Holdenter for Just cynt

DRAFT JTCollins:si 1/21/80

MEMORANDUM FOR: R. H. Vollmer, Director

NRC/TMI Technical Support Staff

FROM:

J. T. Collins, Deputy Director NRC/TMI Technical Support Staff

SUBJECT:

GPU REORGANIZATION

As a follow-up to our meeting with Bob Arnold on Friday, I met with Don Haverkamp to discuss whether or not there were any outstanding open items with reference to GPU organization in previous inspection reports. Attached to this note please find a copy of a recent inspection, in which we have identified that on two previous inspection 7737-01 and 78-17 there are two unresolved items concerning technical specifications to reflect current on-site organizations. With this item still remaining as a outstanding issue it would appear to me that this provides a mechanism for us to delay any action at this time to ugh, have Met-Ed implement in the Restart Program the contents of the new organization. certainly prior to opening of the TMI-1 ReStart hearing.

ултс

These records were reviewed to verify:

- The licensee's onsite organization structure is as described in the Technical Specifications;
- Personnel qualification levels are in conformance with applicable codes and standards;
- Authorities and responsibilities of licensee personnel are as delinated in the Technical Specifications and applicable standards;
- Minimum shift crew composition and licensed personnel requirements are in compliance with Technical Specifications:
- The onsite and offsite safety review committee membership and qualifications are as required by Technical Specifications;
- Change in organization and structure have been reported to the NRC as required by Technical Specifications.

The inspector used the following acceptance criteria for the above items .

- Technical Specifications 6.1, 6.2, 6.3, 6.5.1, 6.5.2B.
- ANSI N18.1-1971 Standard for Selection and training of Personnel for Nuclear Power Plants.
- ANSI N18.7-1972 Standard for Administrative Controls for Nuclear Power Plants.

The inspector noted the onsite organization was not structured as shown in Fig. 6.1 of the Technical Specifications. The licensee indicated that a new organization chart had been submitted with Proposed Technical Specification Change Request 82. The inspector verified the onsite organization was structured as shown on Fig. 6-2 of PTSCR 82. This item will remain unresolved pending review by NRR of the proposed New organization submitted with PTSCR 109 change. (77-37-01)

(Open) Unresolved Item 289/77-37-01: Revision of Technical Specifichart has been included with Tachnical Specifichart has been included with Technical Specification Change Request No. 81 (MEC letter to NRR, Serial GQL 1051, dated June 16, 1978) as part of the STS submittal. This item will remain unresolved pending review by NRR of the proposed change.