



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

November 24, 1982

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Inadequate Surveillance of
Fire Detection
Instrumentation
LER 82-108/99 L-0
AECM-82/568

NOV 26 1982
P 2: 05
USNRC REGION II
ATLANTA, GEORGIA

During a review of plant surveillance procedures, it was discovered that surveillance requirements for some fire detection instruments, as per Technical Specification 4.3.7.9.1, had not been met. An LCO was entered in accordance with Technical Specification 3.3.7.9. This report is being submitted pursuant to Technical Specification 3.3.7.9.b. Attached is LER 82-108/99 L-0 with supplementary information.

Yours truly,

John Richardson
FOR J.P. Mc Gaughy JR.

JPM:sap
Attachment

- cc: Mr. N. L. Stampley (w/a)
- Mr. R. B. McGehee (w/o)
- Mr. T. B. Conner (w/o)
- Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

IE22

821202/050 821124
PDR ADJCK 05000416
S PDR