CONNECTICUT YANKEE ATOMIC POWER COMPANY

P. O. BOX 270 HARTFORD, CONNECTICUT 06101

TELEPHA: 203-66 . 4 1

November 24, 1982

Docket No. 50-213 B10620

Director of Nuclear Reactor Regulation
Attn: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
U. S. Nuclear Regulatory Commission
Washington, DC 20555

References:

- (1) W. G. Counsil letter to D. L. Ziemann, dated March 23, 1979.
- (2) W. G. Counsil letter to D. L. Ziemann, dated December 26, 1979.
- (3) W. G. Counsil letter to D. M. Crutchfield, dated March 31, 1982.
- (4) W. G. Counsil letter to D. L. Ziemann and R. W. Reid, dated August 15, 1979.

Gentlemen:

HADDAM NECK PLANT SAFEGUARDS CONTINGENCY PLAN

Pursuant to 10CFR73.40(b), Connecticut Yankee Atomic Power Company (CYAPCO) submitted Revisions 0, 1, and 2 to the Safeguards Contingency Plan for the Haddam Neck Plant in References (1), (2), and (3), respectively.

CYAPCO hereby submits six (6) copies of Revision 3 to the Safeguards Contingency Plan for the Haddam Neck Plant for review and approval.

A list of Safeguards Contingency Plan sections altered by Revision 3 is included as Attachment 1; the revised pages are included as Attachment 2.

* SOO!

SAFEGUARDS INFORMATION

ATTACHMENTS CONTAIN SAFEGUARDS INFORMATION.
UPON SEPARATION THIS LETTER IS DECONTROLLED.

Pursuant to 10CFR73.21(b), the Safeguards Contingency Plan is considered Safeguards Information, and as such CYAPCO requests the Safeguards Contingency Plan be witheld from public disclosure pursuant to 10CFR2.790(d).

The appropriate amendment fee required by 10CFR170.22 for NRC Staff review and approval of the Safeguards Contingency Plan was previously submitted in Reference 4.

Should you have any questions on this matter, please feel free to contact us.

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY

W. G. Counsil

Senior Vice President

By: N. P. Cagnett

Vice President Nuclear and Environmental Engineering

Attachments

SAFEGUARDS INFORMATION

ATTACHMENTS CONTAIN SAFEGUARDS INFORMATION.
UPON SEPARATION THIS LETTER IS DECONTROLLED.