LICENSEE EVENT REPORT

CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M A P P S 1 2 0 0 - 0 0 0 0 - 0 0 3 1 1 1 1 1 4 5 57 CAT 58
CON'T O 1 SOURCE L 6 0 5 0 - 1 0 2 9 3 7 1 0 2 8 8 2 8 1 1 1 2 6 8 2 9 7 8 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 On 10/28/82, while troubleshooting a ground indication for the 125 VDC circuit.
0 3 the "A" Recirculation Pump MG set was inadvertently tripped. Single loop operation
0 4 is limited to 24 hours by PNPS License Section 3.E. A power reduction was initiated
0 5 and terminated one hour later when the tripped MG set was made operable. The NRC
0 6 was notified via ENS. This event caused no threat to the public health and
0 7 L safety.
0 8 0
7 8 9 SYSTEM CODE CODE SUBCODE C B 11
SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE NO. NO
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. SUPPLIER SUBMITTED FORM SUB. SUPPLIER SU
1 0 Information available to maintenance personnel performing the troubleshooting was
inadequate in that it did not indicate that a link existed between the control
1 2 circuits for the "A" Recirculation MG set and the circuits being investigated.
To preclude a recurrence, this information is being upgraded and personnel have
been counseled to take extra time to trace circuits if a question exists.
PACILITY STATUS OTHER STATUS OF DISCOVERY DESCRIPTION (32) 1 5 E (28) 0 9 8 (29) NA (31) Troubleshooting
7 8 9 10 12 13 44 45 46 ACTIVITY CONTENT AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
1 6 Z 3 Z 34 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 NA 7 8 9 PERSONNEL INJURIES 13 80
NUMBER DESCRIPTION OF
1 8 9 11 12 NA 80
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA 80
PUBLICITY 8212060220 821126 NRC USE ONLY PDR ADDCK 05000293
2 0 n 44 S PDR 68 69 80-5
G. G. Whitney PHONE (617) 746-7900