

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-367/82-02(DPRP)

Docket No. 50-367

License No. CPPR-104

Licensee: Northern Indiana Public Service Company
5265 Hohman Avenue
Hammond, IN 46325

Facility Name: Bailly Generating Station, Nuclear-1

Inspection At: Bailly Site

Inspection Conducted: November 16, 1982

Inspector: *P.R. Pelke*
P. R. Pelke

11/24/82

Approved By: *J. E. Konklin*
J. E. Konklin, Chief
Projects Section 1A

11/24/82

Inspection Summary

Inspection on November 16, 1982 (Report No. 50-367/82-02)(DPRP)

Areas Inspected: Site restoration activities.

Results: No items of noncompliance or deviations were identified.

DETAILS

1. Persons Contacted

Northern Indiana Public Service Company (NIPSCO)

D. Kuhn, Manager, Bailly Generating Station
W. Elliott, Manager, Plant Engineering and Construction
M. Maazel, Structural Engineer

U. S. Department of Interior

D. Wilcox, Hydrologist, Indiana Dunes National Lakeshore

Others

W. Eichhorn, Attorney, Eichhorn, Eichhorn, and Link
R. Vollen, Attorney, Businessmen for the Public Interest
C. Read, Save the Dunes National Council
H. Read, Izaak Walton League

2. Functional Areas Inspected

The inspector was present for the final site restoration inspection pursuant to the May 6, 1982 Order of the Atomic Safety and Licensing Board. Backfilling of the excavation is complete. This was the only work remaining to be accomplished. Site restoration has been accomplished on schedule and in compliance with the Board Order.

3. Exit Meeting

No formal exit meeting was convened. Discussion of the site restoration project was held amongst all mentioned under "persons contacted" during the site tour.