

Appendix

NOTICE OF VIOLATION

Saginaw General Hospital

License No. 21-00607-04

As a result of the inspection conducted on November 19, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:


10 CFR 20.201(b) requires that each licensee make such surveys as may be necessary to comply with 11 sections of Part 20. As defined in 10 CFR 20.201(a), "survey" means an evaluation of the radiation hazards incident to the production, use, release, disposal, or presence of radioactive materials or other sources of radiation under a specific set of conditions.

Contrary to the above, surveys were not made to assure compliance with 10 CFR 20.105(b), a regulation which limits radiation levels in unrestricted areas. Specifically, on November 16, 1982, surveys were not made in the hallway adjacent to an iodine-131 therapy patients room. This is an unrestricted area where radiation levels could have exceeded 2 millirems per hour.

This is a Severity Level IV violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

12/7/82  
Dated

  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2

8212100204 821207  
NMS LIC30  
21-00607-04 PDR