P.O. BOX 529100 MIAMI, FL 33152



FLORIDA POWER & LIGHT COMPANY

50-250

December 3, 1982

PNS-LI-82-486

Mr. James P. O'Reilly Regional Administrator, Region II U. S. Nuclear Regulatory Commission 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-82-15

22 DEC 8 AS. 41

٠

TURKEY POINT UNIT 3

DATE OF OCCURRENCE: NOVEMBER 4, 1982

TECHNICAL SPECIFICATION 6.9.2.b.2

3A HIGH HEAD SAFETY INJECTION PUMP

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

William

J. W. Williams, Jr. Vice President Nuclear Energy

JWW/PLP/mpc

Attachment

cc: Director, Office of Inspection and Enforcement (30) Harold F. Reis, Esquire File 933.1 TP

8212100219 821203 PDR ADDCK 05000250 S PDR

TE 22

PEOPLE ... SERVING PEOPLE