. February 22, 1994



## GEOTECHNICAL SERVICES: DESIGN . CONSTRUCTION . FORENSIC

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

FAX: 301-504-2080

Reply to Notice of Violation, Docket #030-28681, License #15-23181-01

This letter is in response to the above-referenced notice of violation. We were given this violation for a failure to maintain a maximum interval of 6 months between sealed source leak tests. We have corrected this by adopting two designated one-month intervals. June and December, in the calendar year, in which all of our gauges will be leak tested. This corrective action will be begun and documented in June, 1994. We are now in compliance with the six-month, maximum, interval.

Frank Comer

Construction Services Manager, RSO

co Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, TX

76011 Fax. No. 817-860-8210

Frank Come

Alpha-Omega Jeofech, Inc. 1701 State Avenue • P.O. Box 2670 Kansas City, Kansas 66110 (913) 371-0000 FAX: (913) 371-5710