

December 2, 1982

Log No. K82-1725 File: RR2 (NP-33-82-68)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 82-056 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: November 4, 1982

Enclosed are three copies of Licensee Event Report 82-056 which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray

Station Superintendent

Tery Donuma

Davis-Besse Nuclear Power Station

TDM/1jk

Enclosures

Mr. Richard DeYoung, Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management and Program Analysis Encl: 3 copies

Mr. Tom Peebles NRC Resident Inspector Encl: 1 copy

8212100229 821202 PDR ADDCK 05000346