



W3F1-91-0134  
A4.05  
QA

February 7, 1991

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Subject: Waterford 3 SES  
Docket No. 50-382  
License No. NPF-38  
Regulatory Guide 1.97 Information

Gentlemen:

By letter dated December 14, 1990 (W3P90-1559) Waterford 3 committed to provide by January 15, 1991 temporary labeling of existing RG 1.97 instruments on the Control Panels. When the work package for the labeling was being prepared, it was noted that there were a couple of items in question. It was decided that the questions should be resolved before the work was started. Quality Notice QA-91-012 was written when the missed date was discovered. However, the resolution of these items was not completed in a timely fashion, and the temporary labeling was not installed by the commitment date.

Waterford 3 personnel notified representatives of the NRC Region IV staff of the circumstance on January 29, 1991. The installation of the labels was completed January 30, 1991.

The on-shift training of the licensed operators will be completed as originally scheduled (February 28, 1991).

If you have any questions please contact L.W. Laughlin at (504) 739-6331.

Very truly yours,

R.F. Burski  
Director, Nuclear Safety

RFB/BGM/ssf

cc: Messrs. R.D. Martin, NRC Region IV  
D.L. Wigginton, NRC-NRR  
E.L. Blake  
R.B. McGehee  
NRC Resident Inspectors Office

A003  
1/0