

DEC 6 1982

Seaman Nuclear Corporation
ATTN: Mr. D. J. Seaman
P.E., President
7315 S. First Street
Oak Creek, WI 53154

License No. 48-12016-01

30-6763

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. J. R. Madera and D. R. Gibbons of this office on November 18, 1982, of activities authorized by NRC Byproduct Material License No. 48-12016-01 and to the discussion of our findings with Mr. Donald E. Stielow and Mr. Scott Seaman at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix,
Notice of Violation

cc w/encl:
Scott Seaman, RSO
DMB/Document Control Desk (RIDS)

RIII
L.M.
Madera/jp
12/2/82

RIII
Gibbons

RIII
Wiedeman
12/7/82

IE HQ FILE COPY

8212100305 821206
NMS LIC30
48-12016-01 PDR

DMB:IE07