

December 2, 1982

Log No. K82-1726 File: RR2 (NP-33-82-70)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 82-057 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: November 5, 1982

Enclosed are three copies of Licensee Event Report 82-057 which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray

Station Superintendent

Temp Muna

Davis-Besse Nuclear Power Station

TDM/ljk

Enclosures

Mr. Richard DeYoung, Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management and Program Analysis Encl: 3 copies

Mr. Tom Peebles NRC Resident Inspector Encl: 1 copy

8212100325 821202 PDR ADOCK 05000346

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

IE22