

Cotter Corporation
General Office

Return to URFO 467-55
WM-22
PDR

DIAL 303-232-8218
9305 WEST ALAMEDA PARKWAY SUITE 201
LAKEWOOD, COLORADO 80226

November 15, 1982

Mr. Albert J. Hazle, Director
Radiation and Hazardous Wastes
Control Division
Colorado Department of Health
4210 East 11th Avenue
Denver, Colorado 80220



Re: Radon-222 Reports for August and September, 1982

Dear Mr. Hazle:

Attached are Radon-222 Reports for August and September, 1982.

TLD chip probes for Cotter's passive radon monitors (PRM's) received for placement in September were improperly prepared by Cotter's outside laboratory, and were returned. The probes already placed in August were left in place through September. When these were collected and inspected, it was found that they also had been improperly prepared.

Radon gas grab samples were taken at several locations during this reporting period. The probes for the PRM's received and placed for October were inspected and appear to be satisfactory.

If you have any questions, please contact me.

Sincerely,

J. P. McCluskey
J. P. McCluskey
Executive Vice President

8212100343 821115
PDR WASTE PDR
WM-22

JPMc/lb

Attch.

cc: J. E. Rothfleisch
J. Cain
T. Smith

File: 1011K8610-46-3



DESIGNATED ORIGINAL

B. Fisher

20862
info only