

FEB - 1 1991

In Reply Refer To:
Licenses: 35-11468-01
 35-11468-02
Dockets: 030-07338/91-01
 030-07339/91-01

Oklahoma Civil Defense Agency
ATTN: Woodrow Goins, Director
P.O. Box 53365
Oklahoma City, Oklahoma 73152

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Messrs. Selvan Rajendran and Gilbert L. Guerra, Jr., of this office on January 7, 1991, of activities authorized by NRC Byproduct Material License Nos. 35-11468-01 and 35-11468-02, and to the discussion of our findings held by the inspectors with members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under the licenses as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspectors.

The inspectors discussed your staff's misunderstanding regarding the letters referenced in the last condition of the licenses. Specifically, they pointed out that application for license renewal may not result in the deletion of old references, especially if the new application does not contain all necessary information from the previous references. If in the future you want old references to be eliminated from your license(s), please make that clear to us. Also, upon receiving your license from NRC after any licensing action, your staff should review the license carefully to ensure that all license conditions are understood and to ensure that we have made all changes that you requested.

No violations were observed for License No. 35-11468-01.

For License No. 35-11468-02 certain of your activities were found not to be conducted in full compliance with NRC requirements. Consequently, you are required to respond to this matter in writing, in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosure, and your response to this letter will be placed in the NRC Public Document Room.

*RIV:NMLS
SRajendran:jt
/ /91

*NMLS
GLGuerra
/ /91

*C:NMLS
WLFisher
/ /91

D:DRSS
ABBeacht
2 / 1 /91

*Previously concurred

9102130062 910201
REC4 LIC30
35-11468-01 PDR

IE-07
11

The response directed by this letter and the accompanying Notice is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed By:
LAWRENCE A. Y^o IDELL *for*

A. Bill Beach, Director
Division of Radiation Safety
and Safeguards

Enclosure:
Appendix - Notice of Violation

cc:
Oklahoma Radiation Control Program Director

bcc:
DMB - Original (IE-07)
RDMartin
ABBeach
LAYandell
MRodriguez, OC/LFDCB (4503)
*WLFisher
*CLCain
*SRajendran
*GGuerra
*NMLS
*MIS System
*RIV Files (2)
*RSTS Operator
*REHall, URFO

*W/766