

APPENDIX A

Harnischfeger Corporation  
Docket No. 99900088/82-01

NOTICE OF VIOLATION

As a result of the inspection conducted on October 18-22, 1982, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and has been categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987 (March 9, 1982):

Section 21.6 of 10 CFR Part 21 dated December 18, 1981, states, in part, "(b) If posting of the regulations . . . is not practicable, the . . . firm . . . may, in addition to posting Section 206, post a notice which describes the regulations/procedures, including the name of the individual to whom reports may be made . . . ."

Contrary to the above, a notice describing the regulations/procedures was not posted along with the previously posted Section 206.

This is a Severity Level V violation (Supplement VII).

Prior to the completion of the inspection, an appropriate notice was posted thus satisfying the requirements of the regulation.