

Colt Industries



**Fairbanks Morse
Engine Division**
701 Lawton Avenue
Beloit, Wisconsin 53511
608/364-4411

December 10, 1982

50-395

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Ill. 60137

Attention: Mr. James G. Keppler, Director, Region III

Subject: Colt Industries-Fairbanks Morse Engine Division
Emergency Diesel Generators
Possible Thermostatic Valve Malfunction
Fail Safe To "Full Cooling Position"
Part 21 Report
Supplemental Report No. 3 - South Carolina
Electric & Gas Co. Summer Station

References: May 25, 1982; June 28, 1982 and September 17, 1982 Part 21
Reports - Robertshaw Valves - same subject


Gentlemen:

The lower overrun assemblies in the Robertshaw valves installed on the Diesel Generator Sets at the South Carolina Electric & Gas Co., Summer Station have been replaced with overrun assemblies utilizing cotter pins to positively lock the nut to the stem.

The units are now free of the reported potential defect.

A copy of this report is being forwarded to the utility involved.

Very truly yours,


J. M. Moriarty
MANAGER UTILITY SALES

JMM:jc

cc: South Carolina Electric & Gas Co.
P. O. Box 764
Columbia, South Carolina 29218
Attention: Mr. Dan Nauman
Manager, Q.A. & Security

U. S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, D.C. 20555

Robertshaw Controls Company
P. O. Box 400
Knoxville, TN 37901
Attention: T. T. Howell, Quality Mgr.

A division of the Colt Industries Operating Corp.

8212210341 821210
PDR ADOCK 05000395
S PDR

DEC 13 1982

IE19