

## MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205 December 14, 1982

JAMES P. McGAUGHY, JR ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Open Penetrations - Fire Seal and Secondary Containment

Interim Report LER 82-027/99 X-1 AECM-82/600

On July 27, 1982, during a special inspection, it was determined that a fire rated seal was not installed in a spare HVAC penetration to the containment exhaust filter train room and that an open penetration existed in the secondary containment. An LCO was entered in accordance with T.S.3.7.7. and T.S.4.6.6.1.a.3 and is being reported pursuant to T.S.6.9.1.13.b. Attached is an interim report, LER 82-027/99 X-1.

Yours truly,

for J. P. M'Gayby

JPM: sap Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

212210367 821214 DR ADOCK 05000416

TE 22