

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

100

December 15, 1982

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, N.W. Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-13 File 0260/15525/15526 PRD-82/23, Interim Report #4. Corroded Terminal Boards AECM-82/598

OFFICIAL COP

1827

Reference: AECM-82/226, 5/21/82 AECM-82/455, 8/6/82 AECM-82/478, 10/18/82

On April 21, 1982, Mississippi Power & Light Company notified Mr. R. Butcher, of your office, of a Potentially Reportable Deficiency (PRD) at the Grand Gulf Nuclear Station (GGNS) construction site. The deficiency concerns corroded terminal boards on pressure transmitters, flow transmitters, and level transmitters utilized in safety related applications at GGNS.

As reported previously, we have determined that this condition is reportable under the provisions of 10CFR50.55(e) because the corroded terminal boards could cause erroneous signals or loss of signals from the transmitters and, therefore, could have affected adversely the safety of operations of the nuclear power plant.

A final report from an independent laboratory on the analysis of a corroded terminal board attributes the corrosion to the presence of moisture. As the transmitters were not supplied with a defect we have concluded that the provisions of 10CFR21 are not applicable.

A final report is expected to be submitted by January 28, 1983, contingent upon locating the source of moisture entering the transmitters.

212210375 82 ADOCK 050004

MAL:dr cc: See page 2

Member Middle South Utilities System

Mr. J. P. O'Reilly NRC

,

4

AECM-82/598 Page 2

S

-

14

cc: Mr. N. L. Stampley Mr. R. B. McGehee Mr. T. B. Conner

.

.

Mr. Richard C. DeYoung, Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Mr. G. B. Taylor South Miss. Electric Power Association P. O. Box 1589 Hattiesburg, MS 39401