

Appendix

NOTICE OF VIOLATION

University Asphalt Company

License No. 12-17493-01

As a result of the routine safety inspection conducted on December 2, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:


License Condition 13.A(1) of License No. 12-17493-01 requires that you test your sealed sources containing byproduct material for leakage and/or contamination at intervals not to exceed six months. Condition 13.B states that records of leak test results shall be maintained for inspection by the Commission.

Contrary to this requirement, it was learned from statements of licensee representatives and the absence of records that leak tests were not performed at the proper intervals from May 29, 1981 to June 17, 1982.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

12-14-82
Dated


D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1