U. S. NUCLEAR REGULATORY COMMISSION

REGION I

DOCKET/REPORT No.

50-322/90-04

LICENS', No. NPF-82

LICENSEE:

Long Island Lighting Company

P. O. Box 618, North Country Road Wading River, New York 11792

FACILITY NAME:

Shoreham Nuclear Power Station

DATES:

August 26 - December 29, 1990

INSPECTORS:

S. Brown, Project Manager, NRR

P. Harris, Reactor Engineer, RI

B. Norris, Project Inspector (Shoreham)
J. Raleigh, Project Engineer, NRR

INSPECTOR:

B. S. Norris

Project Inspector (Shoreham)

Date

APPROVED BY:

L. T. Doerflein, Chief

Reactor Projects Section 2B

Date

AREAS INSPECTED:

Routine, on-site inspection by members of the Region I Office and NRR staff consisting of facility tours, fitness for duty program, system layup review, housekeeping, maintenance observations, modification of ventilation system, physical plant security, and review of licensee reports.

EXECUTIVE SUMMARY

FACILITY STATUS

Shoreham Nuclear Power Station is shut down and defueled. The licensee continues to maintain the facility in a manner consistent with the status of the plant.

The Long Island Lighting Company (LILCo) has been corresponding with the NRC with respect to their desire to ship fuel support castings and peripheral pieces from the reactor vessel. The NRC has responded that LILCo should wait until a possession only license has been issued.

SURVEILLANCE AND MAINTENANCE

The reactor vessel has been drained and placed in a layup condition. LILCo has decontaminated the reactor vessel, reactor cavity, and the dryer separator pit by a combination of manual cleaning and hydro-lazing. The biological shields have been replaced over the reactor cavity.

STAFFING AND STAFF TRAINING

The overall staffing levels at Shoreham remain stable and the morale of the staff continues to be high. The Nuclear Quality Assurance Department was incorporated into the Corporate Quality Assurance Organization.

LILCo has submitted a request for a modification to the Licensed Operator Requalification Program to reduce the scope of the program to reflect the actual conditions of the plant. Additionally, they have requested that they be allowed to delete the simulator requirement from the requalification program.

SECURITY

LILCo has submitted a request to amend the Physical Security Plan to modify the protected area and to eliminate all vital areas. A security guard was accompanied on rounds, he was knowledgeable of his duties and responsibilities.

RADIOLOGICAL CONTROLS

The ALARA and occupational exposure controls programs, and the implementation of the programs, were reviewed. They appear well managed and have been implemented with a proper focus on plant activities. Health Physics coordinates efforts with maintenance to prevent any job holdup time, resulting in more efficient job completion.

EXECUTIVE SUMMARY (cont.)

FITNESS FOR DUTY PROGRAM

The Fitness for Duty Program was reviewed and found to be in accordance with 10 CFR 26. A review of the testing records indicates an excellent trend of negative results with only one pre-badging positive and one random sampling positive out of nearly 1,000 tests.

There were, however, two occurrences of problems with the testing laboratory used by Shoreham. Both of these problems were found by LILCo personnel and reported to the NRC. Both instances had to do with the laboratory contracted by LILCo to analyze the samples. The central receiving department of the laboratory twice redirected the samples from the designated laboratory to another laboratory. LILCo is in the process of taking corrective action to prevent further reoccurrence of the issue. This item is unresolved pending further review.

NUCLEAR REVIEW BOARD MEETING

The Project Inspector observed a portion of the periodic Nuclear Review Board meeting held in December, 1990. The meeting was well organized and the information was presented clearly. Information provided to the board members was consistent with information provided to the NRC on earlier occasions.

COMMISSIONER VISIT

Commissioner Curtiss toured the Shoreham site in November, 1990, and met with representatives from LILCo, the Long Island Power Authority (LIPA), and the New York Power Authority (NYPA).

Shoreham Decommissioning Plan

LIPA has submitted the Shoreham Decommissioning Plan and the Supplement to Environmental Report (Decommissioning), the documents are currently under review.

TABLE OF CONTENTS

		'age
EXEC	TIVE SUMMARY	, i
1.0	FACILITY STATUS	. 1
2.0	SURVEILLANCE AND MAINTENANCE	. 2
3.0	STAFFING AND STAFF TRAINING	. 2
4.0	SECURITY	. 3
5.0	RADIOLOGICAL CONTROLS	. 3
6.0	FITNESS FOR DUTY PROGRAM	. 4
7.0	NUCLEAR REVIEW BOARD MEETING	. 5
8.0	COMMISSIONER VISIT	. 6
9.0	REVIEW OF LICENSEE EVENT REPORTS	. 6
10.0	REVIEW OF REPORTS	. 7
11.0	MANAGEMENT MEETINGS	. 7
LIST	OF ATTACHMENTS	8

DETAILS

1.0 FACILITY STATUS

1.1 General Status

Shoreham Nuclear Power Station (SNPS) has been shut down since 1989 due to an agreement between the State of New York and Long Island Lighting Company (LILCo), the owner and operator of SNPS. The facility is defueled, the fuel is in the spent fuel pool, and most non-essential systems are in a layup condition. The licensee continues to maintain the facility in a manner consistent with the status of the plant.

1.2 Shipment of Reactor Vessel Internals

In a letter dated September 24, 1990, LILCo informed the NRC of their intention to ship 137 fuel support castings and 12 peripheral pieces from the reactor vessel. The NRC responded in a letter dated October 1, 1990, stating that shipment should be delayed until after a possession only license had been issued. In the Commission order of October 17, 1990, CLI-90-08, it was noted that the NRC Staif did not need to perform a review or analysis for resumed operation of Shoreham as a nuclear power plant as an alternative power source under the National Environmental Policy Act (NEPA). On November 8, 1990, LILCo again informed the NRC of their intention to ship the fuel support castings and peripheral pieces; their reiteration was based, in part, on the Commission's decision. The NRC responded, on November 14, 1990, that the shipment of the fuel support pieces required a license amendment, and that an exigent amendment would be processed. LILCo answered on November 16, 1990, that they did not understand the need for NRC authorization, but that they would wait for the approval. A public notice was issued on November 19, 1990, announcing LILCo's intention to ship the castings and peripheral pieces.

On December 11, 1990, LILCo informed the NRC that they had received additional information with respect to the urgency of shipping the support pieces. Based on that new information, LILCo reevaluated and rescinded their initial characterization that the matter of shipping of the fuel support pieces required exigent circumstances.

2.0 <u>SURVEILLANCE AND MAINTENANCE (37700, 42700, 54834, 61726, 62703, 71707, 71710, 71715, 86700)</u>

The inspectors reviewed the below activities to verify that work was being done in accordance with approved procederes, that systems were properly returned to service, and that Quality Control was involved, as required. During this process, the associated procedures listed in Attachment 1 were reviewed.

2.1 Reactor Vessel Draining

LILCo drained the reactor vessel during the reporting period in preparation for placing the vessel in a layup condition and eventual decontamination of the vessel and associated reactor coolant systems. One of the concerns prior to the draining was the potential radiation levels when the shielding effect of the water was removed. Results showed that the highest readings were less than 3mr/hr. LILCo is attempting to maintain humidity below 35% within the vessel by attaching dehumidifiers to the recirculation loops. Work was performed in accordance with the associated procedures and appropriate radiological precautions were taken to minimize exposure to the workers. No problems were noted within this area.

2.2 Decontamination Efforts

LILCo cleaned and decontaminated the reactor vessel, reactor cavity, and the dryer separator pit. The methods were a combination of manual cleaning and hydro-lazing with a high pressure stream of water. The inspector monitored portions of the activities and noted that the personnel were familiar with the procedures and the equipment. The final portion of the cleaning was accomplished with the hydro-lazing equipment. The biological shield blocks have been returned to cover the reactor cavity. No problems were noted within this area.

2.3 Housekeeping

LILCo has made a concerted effort to maintain the cleanliness of the plant. Areas that the inspector noted as being a problem due to trash collecting and surface deterioration of some of the components were discussed with plant management, these areas especially showed improvement during the inspection period.

3.0 STAFFING AND STAFF TRAINING (36800, 41701)

3.1 Staffing Levels and Organizational Changes

Although there are slight oscillations is the manning of specific departments, the overall staffing levels at Shoreham remain stable. The morale of the staff continues to be high.

During the reporting period, the Nuclear Quality Assurance Department (NQAD) was integrated into the LILCo Corporate Quality Assurance Organization. The Manager, NQAD, will report to the Manager of Corporate QA for policy, personnel, and administration; for daily operational matters, the Manager, NQAD, continues to report to the Vice President, Offices of Corporate Services and Nuclear. The NQAD will remain physically on site.

The Safety Engineering and Reliability Division has been dissolved. The division's responsibilities have been reassigned or have been determined to be no longer applicable to operation of the Shoreham station. One reassignment of note is the Independent Safety Engineering Group, which was reassigned to report directly to the Manager, NQAD.

3.2 Modification to the Licensed Operator Requalification Program

On August 31, 1990, LILCo has submitted a request for a modification to the Licensed Operator Requalification Program. The request actually contains two requests: (1) LILCo requests that they be allowed to revise the training program for the licensed operators to reflect the actual condition of the plant. Currently, they are required to maintain a requalification program as if the plant was operating at 100% power; this is based on the fact they still possess a full power license. (2) The other part of the request is that they be exempted from the requirement that they use a simulator as part of the licensed operator requalification training program. This request is under review by NRR. Pending approval, LILCo continues to abide by the requirements of the requalification program.

4.0 SECURITY (81018, 81700)

On October 9, 1190, LILCo has submitted a request to amend the Physical Security Plan. The proposal is requesting to modify the protected area and to eliminate all vital areas; additionally, the proposal would institute a "secured area" and "special security areas" and would relocate the access controls. This general description is not Safeguards Information per 10 CFR 73. This request is also under review by NRR.

The inspector accompanied a security guard on his normal rounds to assess his knowledge of the responsibilities and duties of the security force. The areas observed were the boundary of the protected area and the outside buildings. The guard was knowledgeable of his duties and responsibilities. No problems were noted within this area.

5.0 RADIOLOGICAL CONTROLS (83728, 83750)

The inspector noted that the occupational exposure controls and ALARA programs appear will managed and have been implemented with a proper focus on plant activities. The HP efforts have been coordinated with maintenance as to prevent any job holdup time. This results in more efficient job completion.

The ALARA program appears well managed with a good interface with all parties involved with a job that has the potential to subject personnel to an exposure. However, due to an initial low estimate for the quarter and extensive efforts to reduce the external radiation levels of shipping casks containing the damaged nuclear instrumentation detectors to well below the Department of Transportation limits, the third quarter 1990 ALARA goals were exceeded.

The inspector did not identify any concerns with the radiological controls programs or the activities observed.

6.0 FITNESS FOR DUTY PROGRAM (2515/106)

6.1 Review of the Fitness for Duty Program

The inspector reviewed the recently approved Fitness for Duty (FFD) Program and the alcohol and drug screening procedures and found them to be in accordance with 10 CFR 26. Although there had been delays in the actual testing times due to administrative problems with a local health service, the program appears to be well managed and implemented. The problem with the testing times has been rectified. A review of the testing records indicates an excellent trend of negative results with only one pre-badging positive and one random sampling positive out of nearly 1,000 tests. The alcohol testing is performed using state of the art equipment.

6.2 Discrepancies Identified with Roche Laboratories

There were, however, two occurrences of problems with the testing laboratory used by Shoreham. Both of these problems were found by LILCo personnel and reported to the NRC. The two occurrences are related and may be generic to other licensees who use the same laboratory; NRR and Region I are evaluating the generic implications:

First Occurrence

In early December, 1990, during an internal audit of the FFD program by the QA department, it was noted that a Roche laboratory other than the LILCo approved laboratory had analyzed the samples. At this time, Shoreham was using a Roche laboratory located in Columbus, Ohio, and the samples were sent to a Roche laboratory located in Triangle Square, North Carolina. Coincidentally, during this same time frame, the laboratory in Triangle Square had been suspended from the National Institute on Drug Abuse (NIDA) list of certified drug testing laboratories. All of the samples were initially reported as negative. LILCo took immediate corrective action to have the samples reanalyzed and confirmed negative. Furthermore, LILCo discussed this with Roche management and came to the conclusion that it was a mistake on the Roche personnel in the central receiving and distribution center. Since this appeared to be an isolated occurrence, Shoreham felt that the corrective action taken was appropriate.

Second Occurrence

Although the second occurrence was after the close of the inspection period, it is being discussed here for continuity. Subsequent to the previous occurrence, the laboratory in Columbus, Ohio, lost its certification and the one in Triangle Square reacquired its certification; consequently, LILCo amended its contract with Roche to use the laboratory in Triangle Square. In January of this year, during a review of the analysis results by LILCo personnel, they noted that the analysis had again been performed by a laboratory other than the one it contracted. Roche Laboratories had built a new laboratory in Rariton, New Jersey, and was also utilizing this new facility as its central distribution center. The Rariton

laboratory is certified, but was not inspected by LILCo. When the samples were received from LILCo at the Rariton facility, a decision was made by the distribution people to have the analysis done at Rariton vice Triangle Square. LILCo supplied the address labels for the samples to assure they are sent to he contracted laboratory, but the address label was evidently ignored. All samples were reported negative.

After the second occurrence, LILCo has taken measures to minimize the chance of additional occurrences. (1) LILCo has developed a new mailing label that specifically states that the package is to be opened only by the indicated laboratory. (2) LILCo has planned a Quality Assurance inspection of the Rariton facility to determine if the facility meets the requirements of the Shoreham Fitness for Duty Program; if the results of the inspection are not satisfactory, LILCo intends to have the samples reanalyzed. (3) LILCo has planned a QA inspection of a second certified facility to allow for a backup laboratory in the event of another reoccurrence by Roche Laboratories. In both instances LILCo notified the NRC of the problem and corrective actions. This issue remains unresolved (50-322/90-04-01) pending NRC review of the effectiveness of these corrective actions and generic applicability.

7.0 NUCLEAR REVIEW BOARD MEETING (40500)

The Nuclear Review Board held its periodic meeting on December 12-13, 1990, at the Shoreham site. The Project Inspector observed a portion of the meeting held of the second day. The portion observed included:

- Shoreham Outlook Summary
- Nuclear Operations Support Department Overview
- License Transfer Status
- Plant Staff Overview
- Decontamination Program
- Briefing of the Status of Rancho Seco and Fort St. Vrain
- Nuclear QA Overview
- Nuclear Engineering Overview
- Spent Fuel Disposition

The inspector noted that the composition of the board was in accordance with the Technical Specifications. The meeting was well organized and the information was presented clearly. Questions asked by the board members were answered consistent with information provided to the NRC on earlier occasions by LILCo. The meeting was effective in that the board members were encouraged to express any concerns they had; additionally, the board members openly responded to all questions with a direct answer. Handouts associated with the NRB meeting are included as Attachment 3 to this report. No concerns were identified by the inspector.

8.0 COMMISSIONER VISIT

Commissioner Curtiss visited the Shoreham site on November 13, 1990, to tour the facility and meet with representatives from LILCo, the Long Island Power Authority (LIPA), and the New York Power Authority (NYPA). Commissioner Curtiss was accompanied by his Legal Assistant, his Technical Assistant, the Regional Administrator-Region I, the NRR Project Manager, and the Project Inspector-Shoreham.

The plant tour was conducted by the Shoreham Plant Manager. Accompanying the Commissioner and his party were the LILCo Vice President, Office of Nuclear, the Shoreham Manager of Quality Assurance, the Counsel for LIPA, and the NYPA Resident Manager. The tour included the diesel generators, control room, reactor building, refueling floor, containment, turbine building, radiological waste building, and the outside auxiliary buildings.

Following the plant tour, discussions were held where in LILCo/LIPA/NYPA personnel discussed current plant status, nuclear quality assurance, spent fuel disposal plans, LIPA and the license transfer efforts, the decommissioning plan and schedule, and the ongoing licensee activities. Copies of the handouts from the discussions are included as Attachment 2 to this report.

9.0 REVIEW OF LICENSEE EVENT REPORTS (LERS) (90712, 92700)

The below listed LERs were submitted to the NRC:

LER No. LER Date Event Date	Subject
90-005, Rev 0 08/29/90 04/18/90	Failure of Primary Containment Electrical Penetration Assembly Modules
90-006, Rev 0 08/31/90 08/20/90	Inoperability of Ultimate Heat Sink
90-007, Rev 0 09/28/90 09/07/90	Unplanned Actuation of Engineered Safety Feature Systems During an I&C Surveillance Test
90-008, Rev 0 10/05/90 09/15/90	Unplanned Actuation of Engineered Safety Feature Systems Due to a Lighting Strike

The inspector reviewed each of the LERs to verify that the details were clearly reported, and that the corrective action was adequate. The review also considered whether further investigation was required, if generic implications were indicated, and whether on-site follow-up was warranted. It was determined that there was no common root cause. The inspector had no further questions with respect to these reports.

10.0 REVIEW OF REPORTS (90713)

10.1 Periodic and Special Reports

The reports listed in Attachment 1 were reviewed to verify that the information was technically adequate, submitted in a timely manner, and satisfied the appropriate reporting requirements, as required. No problems were observed in this area.

10.2 Shoreham Decommissioning Plan

On December 29, 1990, LIPA submitted the Shoreham Decommissioning Plan, per 10 CFR 50.82(a), and the Supplement to Environmental Report (Decommissioning), per 10 CFR 51.53(b). These documents are currently under review.

11.0 MANAGEMENT MEETINGS (30702, 30703, 94702)

11.1 LILCo Drog in Visit

Mr. John Leonard visited the regional office on September 11, 1990, to update the NRC on the status of Shoreham and projected schedules for upcoming activities. The drop-in visit was documented in a letter to LILCo, with the topics of discussion listed. The letter and its enclosure are included in this report as Attachment 4.

11.2 Exit Meeting

The issues within this report were discussed with licensee management throughout the inspection period. A verbal summary was provided by Mr. B. Norris to Mr. L. Calone, Plant Manager, at a meeting on December 14, 1990, at the Shoreham site. A copy of a news release was given to the Plant Manager on October 25, 1990, relating to a laboratory used for drug analysis being temporarily suspended from the qualified list. Based upon the NRC Region I review of this report and discussions with licensee representatives, it was determined that this report does not contain any proprietary information or safeguards information subject to 10 CFR 2.790 restrictions.

LIST OF ATTACHMENTS

Attachment 1 Documents Reviewed

Attachment 2 Handouts from Commissioner Curtiss' Visit to Shoreham

Attachment 3 Handouts from the NRB Meeting on Dec. 13, 1990

Attachment 4 Letter Documenting Drop-In Visit by John Leonard, LILCo

Attachment 1 Documents Reviewed

ATTACHMENT 1

DOCUMENTS REVIEWED

LILCO NED SAFETY EVALUATION REPORTS

88-076, Rev 1	90-023, Rev 0	90-031, Rev 0
89-026, Rev 0	90-025, Rev 0	90-032, Rev 0
89-037, Rev 0	90-027, Rev 0	90-033, Rev 0
89-061, Rev 0	90-028, Rev 0	90-035, Rev 0
90-015, Rev 0	90-030, Rev 0	

LILCO DEFICIENCY REPORTS

Closed			Open	
89-139	90-053	90-084	90-101	90-108
90-025	90-067	90-088	90-102	90-109
90-030	90-070	90-090	90-103	90-110
90-032	90-075	90-098	90-104	90-123
90-038	90-077	90-102	90-105	
90-043	90-078		90-106	
90-045	90-080		90-107	

RADIOLOGICAL INCIDENT REPORTS

- 90-01
- 90-02

QUALITY CONTROL SURVEILLANCE INSPECTION REPORTS

	SI-90-132	Housekeeping on Refueling Floor
	SI-90-134	Maintenance & HP During Disassembly of MOV-040 for Radiological
•	SI-90-140	Characterization Maintenance & HP During Disassembly of MOV-041 for Radiological Characterization
•	SI-90-148	Radwaste Material Handling

QUALITY CONTROL SURVEILLANCE REPORTS

90-073	Radioactive Waste Shipping
90-096	Site Structural Characterization & Decontamination Phase
90-097	Site Structural Characterization & Decontamination Phase
30-093	Radioactive Waste Shipping

ATTACHMENT 1 (cont.)

DOCUMENTS REVIEWED

NUCLEAR QUALITY ASSURANCE REPORTS

- NOAD Audit Schedules for 1990 & 1991
- · Audit Program Status Report for 1990
- NRB Program Audit Status Report for 1990
- Open Audit Finding and Corrective Action Report Status as of 12/07/90
- Quality Hotline Program Status Report for 1990
- Deferred Audit Finding Status Report as of 12/07/90

PROCEDURES

- SP-23.621.02, Rev 0 Reactor Vessel Draining
- Fitness for Duty Program, Rev 1
- Standing Order 25, Rev 22 Operator Duties
- Applied Science & Technologies (ASTEC) procedure for the use of Water Blasting (Hydro-Lazing) to clean the contaminated portions of the reactor vessel and cavity, and the dryer-separator pit

OTHER REPORTS

- Safeguards Event Log for July 1, 1990 through September 30, 1990
- LILCo response to NRC Information Notice 88-23, Supplement 3
- LILCo response to NRC Information Notice 88-63, Supplement 1
- LILCo response to NRC Information Notice 90-48
- LILCo response to Generic Letter 89-10, Supplement 3
- LILCo memorandum (NSD-90-1800, dated Nov 2, 1990) clarifying use of carbon steel lock washers for installation of diesel generator crankcase pressure sensor, and associated Engineering & Design Coordination Report H-1378 and Purchase Order-384123

MONTHLY OPERATING REPORTS

- August
- September
- October
- November

Attachment 2

Handouts from

Commissioner Curtiss'

Visit to Shoreham

SHOREHAM NUCLEAR POWER STATION

COMMISSIONER CURTISS VISIT TO SHOREHAM NOVEMBER 13, 1990

OFFICE OF NUCLEAR OBJECTIVES

- ESTABLISH LEAST COSTS POSTURE CONSISTENT WITH MAINTAINING OPERATING LICENSE
- ENSURE ALL EXPENDITURES ARE PRUDENT AND CONSISTENT WITH TERMS OF THE AGREEMENT
- MEET REQUIREMENTS OF EXISTING 100% LICENSE (AND SUBSEQUENT OL AMENDMENTS) THAT MUST BE CONTINUED GIVEN PLANT STATUS
- OBTAIN A POSSESSION ONLY LICENSE (POL)
 WITH REDUCED TECHNICAL SPECIFICATIONS
- . TRANSFER "LICENSE" TO LIPA/NYPA

LILCO

A.F. EARLEY, JR.
PRESIDENT

J.D. LEONARD, JR. VP, COPR. SERVICES & VP, NUCLEAR

L.J. CALONE PLANT MANAGER

R.M. KASCSAK MANAGER, NUCLEAR ENGINEERING DEPT.

R. GUTMANN MANAGER, NUCLEAR OPS SUPPORT DEPT

W.M. MALOHEY MANAGER, NUCLEAR QUALITY ASSURANCE 8.8 SKORUPSKI ASST. VP & DIRECTOR OF TRAINING

J.M. KELLY MANAGER, CORPORATE QUALITY ASSURANCE

D.M. CROCKER MANAGER, EMERGENCY PREPAREDHESS

W.J. TUNNEY MANAGER, NMP-2 OVERSITE GROUP

J.J. McCARTHY SUPERVISOR, HDS GROUP GROUP VP, EMGINEERING & OPS VP, ENGINEERING

J.P. NOVARRO MANAGER, POWER ENGINEERING

K.D. SMALLING MANAGER, ELECTRICAL ENGINEERING

MANAGER, CIVIL & ARCH. ENGINEERING

MANASER, ENVIRONENTAL ENGINEERING


P8C10904

OFFICE OF NUCLEAR MAJOR ACTIVITY HIGHLIGHTS

8/89 STAFFING ASSESSMENT 8/89 . DEFUELING 12/89-3/90 · SYSTEM LAYUP PROGRAM RADIOLOGICAL SAFETY ANALYSIS FOR 12/89 SPENT FUEL STORAGE & HANDLING . DEFUELED SAFETY ANALYSIS REPORT 1/90 SITE CHARACTERIZATION STUDY 2/90-5/90 . REMOVAL & SHIPMENT OF RADIOACTIVE 4/90 MATERIAL COMPONENTS FUEL INSPECTION 8/90 DECOMMISSIONING INFORMATION (LILCO) 9/90 DECONTAMINATION PROGRAM 12/90

POICEOSA

OFFICE OF NUCLEAR LILCO PERSONNEL




Total Auth Pers

Pers as of 12/31/89 Pers as of 9/30/90

Post Defue! Staff

P8010908

TOTAL PERSONNEL LILCO & CONTRACTORS



P8010906

OFFICE OF NUCLEAR MAJOR LICENSING SUBMITTALS

I APPROVED


· INSURANCE EXEMPTION	4/30/90
· APPENDIX "J" TESTING	6/25/90
. SECURITY PLAN REVISION	6/14/90
· REVISED LERO PLAN	7/31/90
. FITNESS FOR DUTY EXEMPTION	8/21/90

II PENDING

- REMOVAL OF OPERATING AUTHORITY (POL) (INCLUDING TECHNICAL SPECIFICATIONS)
- . TDI 5 YEAR OVERHAUL
- · FIRE PROTECTION PROGRAM CHANGES
- . SECURITY PLAN REVISIONS
- . DECOMMISSIONING FUNDING EXEMPTION
- · ANNUAL USERS FEE
- · OPERATORS REQUALIFICATION CHANGES
- · DELETION OF ISEG
- · LICENSE TRANSFER REQUEST


P010906B

1990 BUDGET PROJECTED YEAR END



P801090F2

1991 BUDGET ESTIMATED



P801090F8

SHOREHAM NUCLEAR POWER STATION

NRC COMMISSIONER CURTISS SITE VISIT
NOVEMBER 13, 1990

PLANT MANAGER'S PRESENTATION OVERVIEW

- . CURRENT PLANT STATUS
- · PLANT LAYUP PROGRAM
- · PLANT RADIOLOGICAL CHARACTERIZATION PROGRAM
- · PLANT DECONTAMINATION PROGRAM
- · LIPA/NYPA LILOO INTERFACE
- · SIJMMARY

CURRENT PLANT STATUS

- . 560 FUEL BUNDLES IN THE SPENT FUEL POOL
- . 300 WATTS DECAY HEAT
- . INCORE INSTRUMENTATION REMOVED/PACKAGED
- . NEUTRON SOURCES REMOVED/SHIPPED TO BNL
- · CONTROL ROD BLADES STORED IN SPENT FUEL POOL
- . FUEL SUPPORT PIECES REMOVED/PACKAGED
- . FOUR FUEL BUNDLES INSPECTED
- . SEPARATOR, DRYER, REACTOR HEAD INSTALLED
- . VESSEL DRAINED/DRY AIR PURGE

PLANT LAYUP

HISTORY

- LILOO N.Y. STATE AGREEMENT
- LILOO COMMITMENT TO NRO
 - FUEL IN THE POOL SCENARIO
 - LAY-UP SOHEDULE

FUEL IN THE POOL SCENARIO (FIPS)

- REVIEW 126 SYSTEMS
- DEFINE SYSTEM CATEGORIES:

. OPERABLE SYSTEMS MAINTAINED TO MEET TECHNICAL SPECIFICATION REQUIREMENTS

· FUNCTIONAL

BASICALLY SUPPORT SYSTEMS NOT REQUIRED PER TECHNICAL SPECIFICATIONS BUT NECESSARY FOR MINIMAL PLANT FUNCTIONS, HABITABILITY, AND PRESERVATION CONCERNS

PROTECTED

SYSTEMS NOT TO BE OPERATED AND WILL BE LEFT IN A PRESERVED, DE-ENERGIZED, AND SAFE STATE

POST SETTLEMENT SYSTEM LAYUP IMPLEMENTATION PROGRAM

. COMPLETION DATE -

SCHEDULED: MAY 11, 1990 ACTUAL: MARCH 30, 1990

- . TYPES OF SYSTEM LAYUP
 - WET SYSTEMS: DRAINED AND DRIED TO 35% RELATIVE HUMIDITY
 - STEAM SYSTEMS: DRAINED AND VENTED, PURGED
 - ELECTRICAL EQUIPMENT: DE-ENERGIZED
 - CONTAINMENT: DRAINED, LOOSE DIRT/SLUDGE
- · LONG TERM MONITORING PROGRAM
 - SCHEDULED MONITORING
 - CONTINUOUSLY PURGED SYSTEMS
 - DEHUMIDIFIED AREAS

TURBINE
MSR
OONDENSER
SUPPRESSION POOL
VESSEL

- UNIQUE LAYUP METHODS

AIR VOIDING CORROSION RESISTANT OILS SELF CONTAINED DEHUMIDIFIER

OPERABLE - (39 Systems)

321 Huclear Boller C7: Reactor Protections Dii Process Radiation Monitoring D21 Area Radiation Monitoring F12 Servicing Alda (Fuei) F15 Refueling G11 Radwaste M43 Fire Protection M50 RBSVS & Cont. Room Chilled Water P41 Service Water P84 Meterorological Monitoring R11 Station Transformer (NSS & RSS) R21 Non-Segregated Buses R22 Metal Clad Switchgear R23 Load Centers and Unit Substations 835 AO Instrument Power R38 AC Uniterruptible (Vital) Power R42 Battery Power (125/DC) R43 Diesel Emergency Power R82 Station Protection and Metering A71 Fire Detect & Station Security R81 Heat Tracing 823 138,89kv Switchyard Pot. Transf. 824 138ky Switchyard Relay Panels T21 Reactor Bulloing 722 Reactor Bullding Superstructure T23 Reactor Primary Containment 731 (AB) Cranes, Holsts and Elevators T41 Reactor Building Ventilation T46 Reactor Bullding Standby Vent U41 Turbine Bulloing Ventilation V41 Regweste Building Ventilation W12 Screenwell Canal X41 MISO HVAC >:60 Diese: Generator Ventilation M61 Control Room Air Concitioning Y25 Barge Dock and Waterfront 294 Selemio Monitoring 196 Post Accident Sampling

FUNCTIONAL - (41 Systems)

G41 Fuel Pool Cool & Cleanup M41 Heating & Aux Boller M42 Domestic Water M44 Sanltarm Sewage MAI Building Service Miso. N34 Lubricating Oli N39 Turning Gear N42 Hydrogen Seal N45 Gen Hydrogen & OO2 Purge 1152 Condensate Demineralizer N71 Olrculating Water OB1 Plant Security P11 Condensate Transfer & Storage P21 Demin & Makeup Water P33 Sample System P43 TBOLOW P60 Compressed Air P71 Low Conduct & SW Drains R24 Motor Control Centers R34 Auxillary Grounding R41 DC Instrument Power (48VDC) 351 Communication (Intra Plant) R62 Comm-Telephone (Leased Line) R63 Comm-Sound (Powered Telephone) R64 Comm-Ragio R65 Closed Circuit TV R61 Unit Protection & Metering 521 Plant Substation 325 69kv Switchyaro Gas Turbine T61 Reactor Building Lighting U31 (TB) Oranes, Holsts, Elevators U5: Turbine Building Lighting V31 RW Cranes, Holats, and Rievators V51 Radwaste Bullding Lighting W23 Chlorination 337 Security Bullding X48 Office Building HVAO X50 Office Bullding Annex X70 Secondary Access Facility 748 Ostnodio Protection Y61 Yard Lighting

PROTECTED - (46 Systems)

B11 Agaotor Assembly 331 Reactor Vister Reciro OT ORD Hypraulic Control C32 Feedwater Control C41 Stanoby Llouis Control
C61 Leutron Instrumentation C6: Reactor Remote Shutdown C91 Process Computer E11 Residual Heat Removal E21 Oore Spray E32 MSIV Leakage Control E45 High Pressure Cociant injection Q33 Reactor Water Cleanup E51 Reactor Core Isolation Cooling M80 Main Chilled Water N11 Main Steam N21 Condensate and Feedwater 1/22 Heater Relief and Vent Lines 123 Miso Drains Secondary Plant N24 Sealing Water N25 Feedbumo TSI N31 Turbine M32 Turbine Control 133 Seal and Radwaste Steam N35 Moisture Separator Rentr & Drains 1136 Extraction Steam N37 Main Turbine Buby Instrument 1141 Generator 143 Generator Stator Cooling 1144 Vacuum Priming & Air Removal 1161 Expitation M62 Radwaste Offgas P42 RBOLOW P83 Radwaste Solids Handling P86 Vibration Monitoring R13 Isolated Phase Bus S11 Main Power Transformer 822 138kv Transfer Breaker T24 Primary Containment Inerting T47 Primary Containment Cooling 748 Primary Containment Atmospheric Control 749 Primary Containment Inter Leak Test 1.62 Control Room Self Cont Air Supply 192 Excess Flow Cheor laives

193 Post Accident Monitoring

PLANT RADIOLOGICAL CHARACTERIZATION PROGRAM

- FOUR AREAS CHARACTERIZED
 - . SYSTEMS AND EQUIPMENT
 - . REACTOR VESSEL AND SHIELD WALL
 - STRUCTURES
 - · SOIL
- PURPOSE
 - OLASSIFIED INTO THREE CATEGORIES
 NON DETECTABLE
 DETECTABLE
 OONTAMINATED
 - ESTABLISHED SOLID BASE
 POSSIBILITY FOR DECONTAMINATION
 EXTENT OF DECOMMISSIONING
 - . NOT A TERMINATION SURVEY

CURTIBO1

PLANT RADIOLOGICAL CHARACTERIZATION PROGRAM

- RESULTS
 - . SYSTEMS AND EQUIPMENT 44/125

RECIRCULATION CONDENSATE DEMIN FUEL POOL CLEANUP RESIDUAL HEAT REMOVAL LIQUID RADWASTE CORE SPRAY REACTOR WATER CLEANUP

SAMPLING

· REACTOR VESSEL AND SHIELD WALL SHIELD WALL MINIMAL ACTIVATION (2 YEARS) REACTOR VESSEL ACTIVATION - 602 CURIES

> 334 CURIES - TOP GUIDE PLATE 170 CURIES - CORE SHROUD 76 CURIES - SRM/IRM GUIDE TUBES 22 CURIES - VESSEL STEEL

REACTOR VESSEL CONTAMINATION

PRESSURE VESSEL VESSEL INTERNALS STEAM SEPARATOR

PLANT RADIOLOGICAL CHARACTERIZATION PROGRAM

- RESULTS

. STRUCTURES - CONTAMINATED

DRYER/SEPARATOR
REACTOR CAVITY/DRYWALL
RADWASTE TRASH LAYDOWN AREA
FUEL POOL
NINE REACTOR BUILDING FLOOR DRAINS
SIX RX BLDG./R.W. BLDG DRAIN SUMPS

- SOILS
 ONE SAMPLE ABOVE BACKGROUND
- OVERALL CONTAMINATION RESULTS
 55 MILLICURIES CON AMINATION

52 MOI - RPV AND INTERNALS 3 MOI - ALL SYSTEMS .2 MOI - ALL STRUCTURES

97% CO-60; 3% MN-54

DECONTAMINATION PROGRAM

TARGET: NE PLANT SYSTEMS

- SEVERAL PLANT AREAS (STRUCTURES)

PROCESS:

. HYDROLAZING 10,000 PSI WATER JET

· MANUAL SCRUBBING

· REGENETIVE DILUTE ACID

OBJECTIVE:

. REMOVE ACTIVATED CRUD AND

CORROSION · AVOID REMOVAL OF BASE METAL IN

PIPING

· AVOID PRODUCTION OF MIXED WASTE

GOAL:

. MINIMIZE WASTE VOLUME TO BURIAL SITE

. MINIMIZE TRANSPORTATION TO BURIAL

SITE

· OVERALL REDUCTION IN COST FOR

DECOMMISSIONING

SUCCESS CRITERIA: UNRESTRICTED RELEASE (RADIOLOGICALLY)

PROGRAM PARTICIPANTS: AND NRB

. OVERVIEW BY SENIOR MANAGEMENT

 PROGRAM MANAGEMENT TASK-FORCE (PLANT STAFF, NED, NQA)

. IMPLEMENTATION BY PLANT STAFF

- PHYSICAL WORK AND SUPERVISION

- VENDOR CHEMICAL PROCESS

LIPAINYPAILILCO INTERACTION

- JOINT SUBMITTALS
- . DECOMMISSIONING REPORT
 - . LICENSE TRANSFER APPLICATION
- COORDINATION MEETINGS
 - . WEEKLY STAFF/FUNOTIONAL AREAS INTERFACE
 - BIWEEKLY LICENSE TRANSFER SCHEDULE UPDATE
 - . EXECUTIVE MANAGEMENT/SENIOR MANAGEMENT STATUS
- MAJOR ACTIVITIES
 - · PROCEDURE REVIEWS
 - · PROGRAM REVIEWS
 - NYPA MANAGEMENT/LILCO STAFF FAMILIARIZATION

NQA OVERVIEW

ASSURANCE OF QUALITY

NUCLEAR QUALITY ASSURANCE PROGRAM UNCHANGED TO DATE

NUCLEAR PROGRAMS ARE ADEQUATE

STAFF IS QUALIFIED AND ADEQUATE

DEFICIENCY REPORT TRENDING


PROGRAM IMPLEMENTATION

- OFFICE OF NUCLEAR PROGRAMS ARE ADEQUATE
 - · VERIFIED BY AUDITS (16 ANNUALLY)
 - · ASSESSED BY TREND REPORTING
- SAFETY EVALUATIONS FOR PROGRAM CHANGES
 - SAFETY EVALUATIONS REVIEWED BY:
 REVIEW OF OPERATIONS COMMITTEE
 NUCLEAR REVIEW BOARD
 INDEPENDENT SAFETY ENGINEERING GROUP
- NUCLEAR QUALITY ASSURANCE PROGRAM
 - VERIFIED ADEQUATE DURING
 ANNUAL INDEPENDENT ASSESSMENT

STAFFING ADEQUACY

- STAFF IS TRAINED AND QUALIFIED
 - . VERIFIED DURING EACH PROGRAM AUDIT
 - VERIFIED FOR SAFETY RELATED MAINTENANCE ACTIVITIES
- STAFF LEVELS ARE ADEQUATE
 - . EVALUATED DURING PROGRAM AUDITS
 - · REVIEWED BY NRC INSPECTION
- STAFF LEVEL TRENDING
 - AUTHORIZED COMPLEMENT REDUCED THROUGH PROGRAM REDUCTION
 - · LILOO COMPLEMENT STABLE
 - . STAFF AUGMENTED BY CONTRACTORS





SHOREHAM SPENT FUEL DISPOSAL

SHOREHAM FUEL CHARACTERISTICS

DESIGN

CONFIGURATION

GE 'C' LATTICE

PELLET DESIGN

NON-BARRIER

ENRICHMENT DISTRIBUTION 76 BUNDLES 0.71 WT %

144 BUNDLES 1.76 WT %

340 BUNDLES 2.19 WT %

CHANNEL THICKNESS

100 MILS

DESIGN BURNUP CORE

712 EFFECTIVE FULL

POWER DAY'S

CURRENT STATUS

DECAY HEAT OUTPUT

300 WATTS

MAXIMUM BUNDLE ACTIVITY 100 R AT CONTACT

7 R AT 3 FEET

CURIES

118,000

BURNUP

2 EFFEOTIVE FULL

POWER DAYS

SHOREHAM FUEL DISPOSAL OPTIONS

- TRANSFER FUEL TO NINE MILE POINT UNIT 2
- . REPROCESS FUEL
- . ON-SITE DRY STORAGE

NINE MILE POINT UNIT 2 OPTION

BACKGROUND

- LILCO PROPOSAL TO COTENANTS APRIL 1990
- LILOO WOULD FUND ALL COSTS FOR TRANSFER OF FUEL TO NINE MILE SITE
- LILCO WOULD SHARE IN FUEL COST SAVINGS

■ PROGRESS

- SNPS FUEL INSPECTION COMPLETED-AUGUST 1990
- S. LEVY TECHNICAL REPORT COMPLETED OCTOBER 1990
 - * FEASIBLE TO PACKAGE AND SHIP FUEL
 - * RISK OF FUEL FAILURE LOW
- NIAGARA MOHAWK NET COST SAVINGS FOR TRANSFER
- SCHEDULE 18-24 MONTHS

. CURRENT ACTIVITIES

- INSTRUMENTATION OF IF-300 DASK
- OOTENANTS MANAGEMENT MEETING NOVEMBER 14

REPROCESSING OPTION

→ BACKGROUND

- REPROCESS FUEL, SELL RECOVERED PRODUCT, KEEP WASTE
- NYPA REQUESTED PROPOSALS FROM BNFL AND COGEMA

· PROGRESS

- TECHNICAL EVALUATION COMPLETE
- FEASIBLE TO LICENSE AND TRANSPORT FUEL
- OVERALL SCHEDULE 24 29 MONTHS
- APPROVAL REQUIRED FROM FRENCH COMPETENT AUTHORITY (FCA), STATE DEPARTMENT, DOT AND N'AC PROJECTED TO TAKE 6 MONTHS

· CURRENT ACTIVITIES

- NYPA CONTINUES DISCUSSIONS WITH COGEMA
- AUTHORIZATION TO PREPARE LICENSE APPLICATION FOR CASK

SHOREHAM SITE DRY STORAGE

- · BACKGROUND
 - STORE ON SHOREHAM SITE UNTIL DOE ACCEPTS FUEL FOR HIGH LEVEL WASTE REPOSITORY
 - NO RETURN TO STORAGE POOL
 - LILCO REQUESTED BIDS FROM 6 VENDORS
- · SUMMARY OF PROPOSALS
 - 4 PROPOSALS RECEIVED
 - SC IEDULES 15 29 MONTHS
 - EVALUATION OF PROPOSALS COMPLETE-OCT. 1990
 - LOW BIDDER PACIFIC NUCLEAR FUEL SYSTEMS (PNFS)
- · CURRENT ACTIVITIES
 - PREPARE GENERIC BWR LICENSE APPLICATION PACIFIC NUCLEAR FUEL SYSTEMS (PNFS)

SHOREHAM FUEL DISPOSAL OPTIONS

SUMMARY

- THREE OPTIONS APPEAR FEASIBLE AND
 HAVE HIGH DEGREE OF SUCCESS
- NINE MILE POINT UNIT 2 TRANSFER IS
 PREFERRED OPTION
- · ALL THREE OPTIONS UNCERTAINTIES
- · CONTINUE TO PURSUE MULTIPLE OPTIONS

LIPA DECOMMISSIONING PLAN

- LIPA AND NYPA ARE WORKING WITH BECHTEL AND TLG ENGINEERING TO DEVELOP A PROPOSED DECOMMISSIONING PLAN.
- * THE PLAN WILL BE SUBMITTED TO THE NRC BY THE YEAR'S END.
- THE DECON ALTERNATIVE APPEARS TO BE THE MOST APPROPRIATE METHOD FOR DECOMMISSIONING THE SHOREHAM PLANT.
- MINIMAL DISMANTLEMENT OF SHOREHAM IS REQUIRED BASED ON THE RESULTS OF A SITE CHARACTERIZATION STUDY.
- . A COST ESTIMATE AND SCHEDULE WILL BE PROVIDED IN THE PLAN.
- THE VARIOUS OPTIONS FOR FUEL DISPOSITION
 WILL BE INTEGRATED INTO LIPA'S DECOMMISSIONING
 PLAN.
- SHOREHAM DECOMMISSIONING IS CONSIDERABLY LESS THAN THE DECOMMISSIONING OF REACTORS WITH SIGNIFICANT OPERATING EXPERIENCE.

ANTICIPATED SCHEDULE FOR DECOMMISSIONING

MILESTONE/ACTIVITY	DATE
LIPA DECOMMISSIONING PLAN SUBMISSION TO THE NRC	DEC 1990
* NRC APPROVAL OF JOINT LIPA/LILCO LICENSE TRANSFER APPLICATION	JUN 1991
LIPA SUBMISSION OF LICENSE TERMINATION APPLICATION TO THE NRC	AUG 1991
• NAC APPROVAL OF DECOMMISSIONING PLAN	OCT 1991
SHOREHAM PLANT DECOMMISSIONING COMPLETE, NRC LICENSES TERMINATED	DEC 1993

LICENSING

ACTIVITIES

FRSTPAGE

LICENSING SUBMITTALS

I APPROVED

· INSURANCE EXEMPTION	4/30/90
· APPENDIX "J" TESTING	6/25/90
. SECURITY PLAN REVISION	6/14/90
· REVISED LERO PLAN	7/31/90
. FITNESS FOR DUTY EXEMPTION	8/21/90

II PENDING

- REMOVAL OF OPERATING AUTHORITY (POL) (INCLUDING TECHNICAL SPECIFICATIONS)
- . TDI 5 YEAR OVERHAUL
- · FIRE PROTECTION PROGRAM CHANGES
- . SECURITY PLAN REVISIONS
- . DECOMMISSIONING FUNDING EXEMPTION
- · ANNUAL USERS FEE
- . OPERATORS REQUALIFICATION CHANGES
- · DELETION OF ISEG
- · LICENSE TRANSFER REQUEST

Post Settlement NRC Amendments/Exemptions PENDING

Actions	Submittel Date	NRC ,	Potential Saving/Yr
Removal of Oper. Auth.	1-06-90	Fending	3.044
(POL)(Including IECH OFECS)	3-16-90	Pending	0.3M
Continuous Fire Watch	6-03-80	Pending	1.0M
Fire Prot. Tech. Spec.	7-20-90	Pending	•
Loense Transfer Request	8-28-90	Pending	
Deletion of ISEG	8-21-90	Pending	0.6M
Rev perator Requal.	8-31-90	Pending	0.5M
Program	0-31-00	Dandlon	OPEN
mental Champ, amended	0-01-00	Danding	1.3M
Security Plan Revisions	10-15-90	Pending	2.0M
	Total Savinge Pending	bulgue	8008

PROBLEMS

- LACK OF TIMELY APPROVAL OF LICENSING SUBMITTALS FOR AMENDMENTS AND EXEMPTIONS
- · REVISED TECHNICAL SPECIFICATION
- NEED FOR ISSUANCE OF POSSESSION ONLY LICENSE
- CONTINUED HIGH COSTS OF MAINTAINING PLANT AND STAFF WITH OPERATING LICENSE
- · LICENSE TRANSFER TO LIPA
- . "CHASING MILLICURIES WITH MEGA BUCKS"
 - MOST SIGNIFICANT DIFFERENCE BETWEEN THIS AND OTHER PLANTS IS THE AMOUNT OF CONTAMINATION AND ACTIVATION

PROBLEM8


Attachment 3
Handouts from the
NRB Meeting

Dec. 13, 1990

NUCLEAR OPERATIONS SUPPORT DEPARTMENT

NAB10901

POST SETTLEMENT NOSD STAFFING



Total Auth Pers

Post Defuel Staff

Pers as of 12/31/89

NRB10208

LICENSING

ACTIVITIES

FRSTPAGE

Post Settlement NRC Amendments/Exemptions PENDING

Actions	Submittal Date	Potential Saving/Yr
Removal of Oper. Auth.	1-05-90	3.0M
(POL)(Including TECH: SPEC'S)		
TDI 5 Year Overhaul	3-16-90	0.3M
Continuous Fire Watch	6-03-90	1.0M
Fire Prot. Tech. Spec.	7-20-90	
License Transfer Request	6-28-90	
Deletion of ISEG	8-21-90	0.6M
Rev Operator Requal. Program	8-31-90	0.5M
Simulator Exemp. amended	8-31-90	0.25M
Annual NRC Users Fee	9-07-90	1.3M
Security Plan Revisions	10-15-90	2.0M
125v D.C. Battery Seismic Exemption Request	Pending	0.3M
TOTAL SAVINGS PEN	DING	9.35M

LICENSING SUBMITTALS

I APPROVED

- INSURANCE EXEMPTION	4/30/90
. APPENDIX 'J' TESTING	8/25/90
. SECURITY PLAN REVISION	6/14/90
· REVISED LERO PLAN	7/31/90
. FITNESS FOR DUTY EXEMPT	ION 8/21/90

II PENDING

- . F.IMOVAL OF OPERATING AUTHORITY (POL)
- . TUI 6 YEAR OVERHAUL
- . FIRE PROTECTION PROGRAM CHANGES
- . SECURITY PLAN REVISIONS
- . DECOMMISSIONING FUNDING EXEMPTION
- . ANNUAL USERS FEE
- . OPERATORS REQUALIFICATION CHANGES
- . DELETION OF ISEG
- . LICENSE TRANSFER REQUEST

NAB121304

LITIGATION U.S. COURT OF APPEALS (D.C. CIRCUIT)

CASE I - DISMISSED

- · Petition filed Oct. 13, 1987
- Requested Court review of NRC action on the two 2 206 petitions
- Court dismissed Jan. 22, 1990 (As NRC action was not a final agency action)

CASE II - PENDING

- · Petition filed May 7, 1990
- · Requested Court review of NRC action on:
 - a) LERO request
 - b) Security request
 - c) Appendix J
 - d) Confirmatory order
 - e) Insurance
- Aug. 30, 1990 Order dismissed a,b & c
 above
- . Thus only d & e are pending

N810_018

LITIGATION U.S. COURT OF APPEALS (D.C. CIRCUIT)

CASE II - PENDING (CONT.)

 Oct. 11,1990 Court Ordered the Following Schedule:

Nov. 20,1990 Patitioner's Brief (SNRSD & SE)

 Dec. 20,1990 Respondent's Brief (NRC)

Jan. 04,1991 Intervenor's Brief (LILCO)

Jan. 18,1991 Petitioner's Reply Brief

Feb. 08,1991 Final Brief

Mar. 11,1991 Oral Argument

EVENTS WHICH DELAYED POL & OTHER REQUESTS

· Sept. 18,1990

DOE Letter

Sept. 20,1990 SWRSD/SE2 Hearing Request

Oct. 09,1990

CEQ Letter

· Oct. 17.1990

Commissionera Memordandum

- · Resumed operation not an alternative to be considered in a NEPA required EIS
- . NRC Staff must ensure LILCO
 - (a) Comply with OL & regulations applicable to defueled mode and
 - (b) Keep all decommissioning options open until Staff approval of a decommissioning plan
- * Forwarded six petitions on three issues to a Licensing Board
 - (a) confirmatory order
 - (b) security amendment
 - (c) LERO exemption/amendment
- Oct. 18,1990 ASLB Established
 - * Morton B. Margulies, Chairman
 - George Ferguson
 - Jerry Kline

POL & OTHER REQUESTS

· Oct. 29,1990	SWRSD/SE2 Files a Joint
	Petition for Reconsideration
	of CLI 90-08 with the Comm.

- Nov. 01,1990 LILCO/PSC interpret CLI 90-0 to permit disposal of equip.
 needed for full pwr operation
- Nov. 08,1990 LILCO informs NRC Staff of o intention to ship the fuel assembly support castings to Barnwell, SC for burial
- Nov 09,1990 NRC Staff(EDO) request Comm.
 guidance with respect to the
 issue of disposal of such equip
 prior to issue of a POL
 RESPONSE IS PENDING
- Nov. 14,1990 NRC Staff considers LILCO's Nov. 08 letter a request to amend our OL under "exigent circumstances"

POL & OTHER REQUESTS

· Nov. 16,1990

NRC Staff meets with NUMARC and states that POLs will be issued after resolution of

(1) funding issues and

(2) programmatic issues (NRC)

Nov. 28,1990

SWRSD/SE2 and DOE oppose the issuance of the amendment

Amendment is pending/fuel support castings are still in the turbine building

· At Present

POL License issue awaiting internal NPC approval of programs & procedures.

Individual amendments / exemptions will be issued prior to resolution of the POL issues

STATUS LIST OF PENDING SHOREHAM REQUESTS

I. LIICO's Requests to the NRC to Implement the Shoreham Settlement

Description of Request	Purpose of Request	Date of Filing	Status
1. DSAR Submittal:			
a) LHLCO's Application for an Amendment to Facility Operating License NPF-82 (S. PC-1664).	To remove LILCO's authorization to operate Shoreham and to allow LILCO to implement a revised set of technical specifications for fuel handling operations and create a Possession Only License.	1/5/90	Pending
b) Revise Set of DSAR T.S. Based on 8/2/90 NRC Meeting (SNRC-1752).	To resolve NRC comments documented in NRC letter 6/27/90 and NRC Meeting on 8/2/90.	8/30/90	Pending
2. TDI Emergency Diesel Generators:			
a) LHLCO's Request for Interim Relief from the One-Time Five Year Inspection Requirement of Paragraph A, Attachment 2 to NPF-82 and Technical Specification Surveillance Requirements 4.8.1.1.2.e2, 3, 4, 5, 6, 7, 8 and 10 pending Disposition of January 5, 1990 License Amendment Application (SNRC-1694).	To allow LILCO to defer performing the one-time five year 25% sample inspection of the emergency diesel generators and to suspend certain emergency diesel generator surveillances, with resulting costs savings.	3/16/90	Pending
b) Revision to Interim Relief Request (SNRC-1694) on TDI EDGs one-time 5 Year Inspection Requirement and Technical Specification Surveillance F-quirements by deleting Tech Spec portion (SNRC-1766).	To allow LILCO to defer performing the one-time five year 25% sample inspection of the emergency diesel generators, with resulting cost savings.	10/23/90	Pending

STATUS LIST OF PENDING SHOREHAM REQUESTS

I. LILCO's Requests to the NRC to Implement the Shoreham Settlement

Description of Request	Purpose of Request	Date of Filing	Status
3. Funding For Decommissioning			
a) LILCO's Request for Exemption (V. Staffieri letter).	To allow LILCO to use the Site Corporation Agreeme in lieu of filing a Funding Report necessary for decommissioning. The Funding Report required by 10 CFR 50.33(K)(2) and 50.75(b) would result in undue hardship and costs to LILCO and its ratepayers.	6/11/90	Pending
4. Operators' Licenses Requirements			
- LILCO's Request for an Exemption From the Operators Licerses Requirements of 10 (FF. 55 (SNRC-1719).	To document the inability to comply with 10 CFR 55. Alleviate LILCO's additional costs associated with the completion of the certification of a plant referenced simulator.	6/5/90	Pending
- As Americal to Revise SNPS Operator licenses Program (SNRC-1749).	 Eliminate the use of the simulator in its entirety. Forwarded LILCO's proposed revision to LILCO's NRC-approved operator requalification training program. 	8/31/90	Pending
5. License Transfer Request			
LILCO's and LIPA's Joint Application for a License Amendment to Authorize the Transfer of Shoreham (SNRC-1734).	To amend Shoreham's license to designate LIPA as the Plant's licensee.	6/28/90	Pending

December 13, 1990

STATUS LIST OF PENDING SHOREHAM REQUESTS

I. LILCO's Requests to the NRC to Implement the Shoreham Settlement

Date of

Description of Request	Purpose of Request	Filing	Status
6. Annual License Fee LILCO's request that the Annual License Fee for FY 1991 for SNPS be held in abeyance pending disposition of LILCO's 1/5/90 license amendment application (SNRC-1754).	Has the potential of saving LILCO \$719,000 annually until a POL is granted.	9/7/90	Pending NRC letter dtd 10/2/90 stated LILCO need not send money pending completion of NRC review.
7. Security Plan LILCO's request to revise Security Plan for Long Term Defueled Condition (SNRC-1762).	To redefine protected area, establish a "Security Area," relocate access control, reduce extent of Plan in 2 phases. To re uce costs.	10/9/90	Pending
8. Deletion of ISEG LILCO's request to amend NPF-82 by deleting ISEG and its associated admin. controls (SNRC-1745).	To provide a significant reduction in LHAO's costs (\$600,000 annually) associated with ISEG.	8/21/90	Pending

STATUS LIST OF PENDING SHOREHAM REQUESTS

II. Other LILCO Request to the NRC Not Related to the Shoreham Settlement

Description of Request	Purpose of Pequest	Date of Filing	Status
1. Fire Protection			
a) Removal of Fire Protection Program from Te-h Specs. Revisions per Generic Letters 36-10 and 88-12 (SNRC-1737).	To conform with GL 86-10 and 88-12 to replace current license conditions with a new standard condition and remove unnecessary fire protection technical specifications.	7/20/90	Pending FR Noti e & Proposed Finding of No Signifi- can't Hazards Consider- ation 9/5/90
b) Revised Attachment 2 (license conditions) based on 9/12 discussions w/S. Brown (NRC) (SNRC-1761).	To eliminate unnecessary reident- ification/r numbering of license.	9/24/90	Pending
c) LILCO's Requests for Interim Relief from: a) establishing continuous fire watches per TS and b) establishing hourly fire watch patrol per TS (SNPC-1721).	A substantial reduction in costs associated with fire watches.	6/5/90	Pending

REQUESTS APPROVED BY NRC


Date of


Description of Request	Purpose of Request	Filing Filing	Approval Date
1) Amendment of OL NPF-82 (Approval of F	rocedures)		
LILCO's Request to Modify the Tech Specs to Remove an Inconsistency in the Plant Procedural Change Approval Process (SNRC-1612).	1) To be consistent with the remaining text of specification 6.8.2.	7/13/89	1/16/90
	2) Relieve the Plant Manager of unnecessary administrative duties.		
2) Amendment of OI NPF-82 (Organization	Chart)		
LILCO's Request in Tech Spec 6.0, Delete Figure 6 2.1-1 Corporate Nuclear Organization.	To modify the Tech Specs to incorporate changes in accordance with Generic Letter 88-06.	6/13/88	2/1/90
LILOO's Request in Tech Spec 6.0, Delete Figure 6.2.2-1, Unit Organization. (SNRC-1465).	Also to modify Tech Spec to achieve consistency within licensing documents and to reflect realignment of corporate management responsibilities and reporting requirements.		
3) Appendix J (Interim Relief) LILCO's Request for an Exemption from the Primary Containment Leak Rate Testing Requirement of 10CFR50.54(o) & Appendix J (SNRC-1692).	To eliminate the need to establish and implement a periodic testing program.	3/13/90	3/16/90
4) Amendment of OL NPF-82 (EDGs)			
LILCO's Request to Modify OL NPF-36 Reduce Test Frequency of the EDGs in Accordance with Generic Letter 84-15 (SNRC-1481).	To improve diesel generator reliability by reducing the number of starts and loads on the EDGs. Change request was submitted in accordance with Generic Letter 84-15.	7/15/88	4/20/90

REQUESTS APPROVED BY NRC

Description of Request	Purpose of Request	Date of Filing	Approval Date
10) Radiological Effluents LHCO's Application for an Amendment to Facility Operating License NPF-82 (SNRC-1666).	To amend Shoreham's Radiological Effluents Technical Specifications to conform to guidance in Generic Letter 89-01.	2/20/90	6/25/90
a) LILCO's Request for an Exemption from the Emergency Preparedness Requirements of 10 CFR 50.54(q) (SNRC-1651).	To allow LILCO to cease offsite emergency preparedness, disband LERO, and implement the Defuel-Emergency Preparedness Plan	12/15/89	7/31/90
b) LILCO's Application for an Amendment to Facility Operating License NPF-82 (SNRC-1651).	To suspend the effect of offsite emergency preparedness license conditions while the plant is in a defueled condition.	12/15/89	7/31/90
c) LHLOO's Request for Interim Relief from the Requirement to Conduct a FEMA Graded Exercise and Request for Deferral of the NRC- Graded Onsite Exercise Pending Dispositon of its Request for an Exemption from the Emergency Preparedness Requirement of 10 CTR 50.54(q) (SNRC-1699).	To eliminate the need for LILCO to conduct a FEMA-graded offsite exercise by the end of 1990 and to defer conduct of an onsite exercise pending NRC approval of LILCO's emergency preparedness exemption request.	3/28/90	7/31/90

IMAGE EVALUATION TEST TARGET (MT-3)













IMAGE EVALUATION TEST TARGET (MT-3)







REQUESTS APPROVED BY NRC

Description of Request	Purpose of Request	Filing	Approval Date
12. Plant Service Water System-Shutdow LOD 3.7.1.2.b.3	<u>n</u>		
LILCO's Request for Interim Relief From Tech Specs Limiting Condition For Operation 3.7.1.2.b.3 (SNRC-1746) (subsequently, SNRC-1750 dated 8/15/90 showed time frame).	To allow LILCO to perform radiation survey and physical inspection of the spent fuel without the need of placing a portion of the RHR System back into its prior condition.	8/10/90	8/16/90
13. Fitness-for-Duty:			
a) LILCO's Request for a Limited Scope Exemption from the Fitness- for-Duty Requirements of 10 CFR Part 26 (SNFC-1689).	To allow LHLCO to limit the scope of the Shoreham Fitness-for-Duty Program to only those personnel with unescorted access to "vital areas," with resulting costs savings and greater administrative convenience.	3/15/90	8/21/90
b) LILCO's Request for Interim Relief Pending Disposition of Exemption (SNRC-1689)	To allow LHLCO to limit the scope of the Shoreham Fitness-for-Duty Program pending of LHLCO's exemption request.	3/15/90	8/21/90 (approval for full exemption as in item a.)



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON D C. 20555

November 29, 1990

G-90285 Recd. 12-04-90

Docket No. 50-267

Mr. A. Clegg Crawford Vice President, Nuclear Operations Public Service Company of Colorado Post Office Box 840 Denver, Colorado 80201-0840

Dear Mr. Crawford:

SUBJECT: COMPONENT REMOVAL ACTIVITIES

CC: JDL

RMK

NMM

LJC F. Your Information

RG

LFB

PGP

\$ LETTE \$1771 BAT 188

\$ f. hear (DEC) \$ 4.5.4.5 \$6. 000

\$ boryson (DEC) \$ 4.5.4.5 \$6. 000

\$ boryson (DEC) \$ 4.5.4.5 \$6. 000

\$ f. corner (DEC) \$ 4.5.4.5 \$6. 000

\$ f. corner (DEC)

- Burds (STGL/S, Tb/S) 5 Silest (SSC) 5 Spring (1887) 6 Shanutt (1867)

By letter dated November 5, 1990 as revised November 7, 1990, you informed the Nuclear Regulatory Commission (NRC) of certain activities that Public Service Company of Colorado (PSC) would accomplish within existing licensee authority oder 10 CFR 50.59 requirements. You advised the NRC that, in addition to component removal activities accepted by the NRC in its June 21, 1990 letter, PSC would dispose of the "B" helium circulator and remove the "A" helium circulator from the PCRV. You also stated that after December 7, 1990, PSC intends to continue with plant closure as it deems appropriate under 10 CFR 50.59 requirements.

The removal of the "A" and "B" circulators was proposed in your letter of May 22, 1990 (item 6). In the staff's response, dated June 21, 1990, we urged that this action be delayed until a possession-only license was issued but offered to reconsider our view in light of any additional information you might wish to provide. With respect to the circulators, such information was presented in your letters of November 5 and 7, 1990. Based on the additional information, we have determined that since you have a spare circulator of site, you may proceed with disposal of the "B" circulator and that you may remove the "A" circulator for on-site retention. Those actions do not constitute irreversible actions with respect to a potential return to power. Other component removal activities should not be accomplished until after the possession-only license is issued unless the proposed action does not constitute an irreversible action with respect to a return to power operations.

Seymons H. Weiss

Seymour H. Weiss, Director

Mon-Power Reactors, Decommissioning and Environmental Projects Directorate

Division of Advanced Reactors and Special Projects

Office of Nuclear Reactor Regulation

cc: ! e next page

SHOREHAM NUCLEAR POWER STATION

NUCLEAR REVIEW BOARD

MANAGEMENT PRESENTATION

DECEMBER 13, 1990

PLANT ACTIVITY OVERVIEW

- MAJOR PLANT ACTIVITIES COMPLETED SINCE OCTOBER
- . MAJOR PLANT ACTIVITIES IN PROGRESS
- MAJOR PLANNED ACTIVITIES
- DECONTAMINATION PROGRAM
- · OTHER ACTIVITIES
- PLANT STAFF LEVEL CHANGES

MAJOR PLANT WORK COMPLETED SINCE OCTOBER

- . REACTOR VESSEL DRY OUT
- . RWCU SYSTEM LAYUP
- . PLANT PROCESS COMPUTER LAYUP
- RBNVS MODIFICATION
- · REACTOR CAVITY CLEANING
- CONDENSATE DEMINERALIZER SYSTEM - FUNCTIONAL
- · CHARCOAL TESTING ON RBSVS
- · REVISED FITNESS FOR DUTY PROGRAM
- . ONE RADWASTE SHIPMENT TO BARNWELL
- . EMERGENCY PLANNING ANNUAL EXERCISE
- DRYWELL HEAD INSTALLED
- . TWO OF SIX CAVITY BLOCKS INSTALLED

MAJOR PLANT ACTIVITIES IN PROGRESS

- . RBSW STRAINER REPAIR B AND C
 - SEISMIC ANALYSIS
 - OPERABILITY/FUNCTIONAL
- LICENSE OPERATOR REQUALIFICATION EXAMS
- RWCU CHARACTERIZATION
- EQUIPMENT LAYUP VERIFICATION
- · RADWASTE SHIPMENTS
 - FUEL SUPPORT PIECES NOT SHIPPED
 - SRM/IRM DETECTORS
- STRUCTURAL DECONTAMINATION
 - REACTOR CAVITY
 - DRYER/SEPARATOR PIT
 - SUPPRESSION POOL
 - TOTAL ORGANIC CARBONS
- SYSTEM DECONTAMINATION
 - REACTOR WATER CLEANUP

MAJOR PLANNED ACTIVITIES

- DECONTAMINATION PROGRAM
- . EDG 101 5 YEAR/18 MONTH OVERHAUL
- · RADIOACTIVE WASTE REMOVAL
 - CONTROL ROD BLADES
 - LPRMS
 - TIPS
 - FSP W/POL
- CONTROL ROD DRIVES REMOVAL/ PRESERVATION
- BEACH REFURBISHING
- . 30 DAY FUEL MOVEMENT READINESS

REACTOR WATER CLEANUP DECON PROGRAM

- DESCRIPTION
- CHARACTERIZATION
- · HYDROLAZING
- · PRESSURE TESTING
- . CHEMICAL PROCESS VENDOR SELECTION
- · PROCESS DEFINED VIA PROCEDURES
- IMPLEMENTATION
- · ANALYSIS
 - RESULTS
 - ECONOMICS
- DECISION

OTHER ACTIVITIES

- . FITNESS FOR DUTY REVISION
- . FEASIBILITY STUDY ON TBOLOW
- . MINIMIZING DRY ACTIVATED WASTE
- LILCO/NYPA INTERFACE
- . LER STATUS: 9 YTD

O OCTOBER

O NOVEMBER

PLANT STAFF LEVELS

HINOM	LILCO	CONSULTANI	TOTAL
JUNE	240	22	262
JULY	240	22	262
AUG	237	19	256
SEPT	237	21	258
OCT	239	21	260
NOV	238	21	259

AUTHORIZED = 260

PLANT STAFF CHANGES

TRANSFERRED				NET	
HINOM	HIRED	IN	OUT	RESIGNED	CHANGE
JUNE	1	4	4	1	0
JULY	5	0	3	2	0
AUG	5	3	6	5	-3
SEPT	2	2	1	3	0
ОСТ	4	2	2	2	2
NOV	0	1	0	2	-1

(DOES NOT INCLUDE CONSULTANTS)

SMUD

1. Status of NRC Submittals

- a. FP Approved
- b. Security Pending
- c. EP Pending
- d. Trg. Pending
- e. Mod. TS Pending (Defueled TS)
- f. Possession only license submittal Pending

2. Plant Status

- a. Core off-loaded.
- b. Vessel flooded to head flange/head on (wet lay up).
- Loops filled to level of vessel flange, N₂ cover on remainder of RCS.
- d. 50 systems identified as "Important to Safety" and remain operational. Primarily related to SFP-Electrical, Mechanical and Radiological. Present TS applied only to these 50 systems.
- e. 150 systems in dry lay-up program, 30 left to do. No decontamination. Primary side systems drained. No purge.
- 9.527 x 10⁶ total curries in plant. Determined by radiological characterization.
- g. Secondary plant in dry layup. Turbine rotated ½ turn manually every two weeks. (Dry layup means continuous air purge, includes main steam (from S/G's) turbine, condenser, main feed.

3. Staffing


a. 400 personnel on site. 100 of which are security personnel.


4. Present Activities

- a. No major activities. Maintaining status quo. Continuing to dry layup remaining 150 selected systems. Awaiting NRC action.
- b. All temporary structures (trailers) being auctioned off and sold. Most are gone.
- All construction activities stopped. Training facility at 90% complete and discontinued. Simulator sold to Crystal River at very low price.
- 5. Future: (When NRC approves defueled TS and other submittals)
 - Reduce manpower to _200 people.
 - b. Prepare decommissioning plan (Bechtel)
 - c. Consider selling diesels (2-2500 kw GM's and 2-3500 kw TDI's).

6. Decommissioning Plan

- Present plan extends to 2050 due to lack of funds need 1 billion dollars.
- b. NRC wants complete funding in 5 years.





Nuclear Engineering Department

OUTLINE

- NED OVERVIEW
- FUEL DISPOSITION STATUS
- NYPA DECOMMISSIONING PLAN

NUCLEAR ENGINEERING DEPARTMENT OVERVIEW

- · STAFFING
 - DURING 1990 STAFF HAS BEEN VERY STABLE
- DEPARTMENT THEMES
 - MAXIMIZE REDUCTION IN REQUIRED ACTIVITIES
 - MINIMIZE COSTS
 - IMPROVE SERVICE TO ALL ORGANIZATIONS
- · PRIORITIES
 - LICENSE REQUIREMENT REDUCTIONS
 - LICENSE TRANSFER
 - DECONTAMINATION PROGRAM
 - PLANT SUPPORT
 - CONFIGURATION CONTROL
 - FUEL DISPOSITION
 - SUPPORT NYPA IN FINALIZATION OF DECOMMISSIONING PLAN
- KEY ACTIVITY IN 1991
 - TRANSITION WITH NYPA
 - · PROJECT PLANNING
 - · PROCEDURES
 - STAFF TRANSFER

SHOREHAM FUEL DISPOSAL OPTIONS

- TRANSFER FUEL TO NINE MILE POINT, UNIT 2
- REPROCESS FUEL
- ON-SITE STORAGE

NINE MILE POINT UNIT 2 OPTION

- · BACKGROUND
 - LILCO PROPOSAL TO COTENANTS APRIL 1990
 - LILCO WOULD FUND ALL COSTS FOR TRANSFER OF FUEL TO NINE MILE SITE
 - LILCO WOULD SHARE IN FUEL COST SAVINGS
- · PROGRESS
 - SNPS FUEL INSPECTION COMPLETED AUGUST 1990
 - S. LEVY TECHNICAL REPORT COMPLETED OCTOBER 1990
 - . FEASIBLE TO PACKAGE AND SHIP FUEL
 - · RISK OF FUEL FAILURE LOW
 - NIAGARA MOHAWK NET COST SAVINGS FOR TRANSFER
 - SCHEDULE 18-24 MONTHS
- · CURRENT ACTIVITIES
 - INSTRUMENTATION OF IF-300 CASK
 - GE SETTLEMENT AGREEMENT
 - ASSIST IN LICENSE AMENDMENT PREPARATION FOR NIAGARA MOHAWK

REPROCESSING OPTION

- BACKGROUND
 - REPROCESS FUEL, SELL RECOVERED PRODUCT, KEEP WASTE
 - NYPA REQUESTED PROPOSALS FROM BNFL AND COGEMA
- · PROGRESS
 - TECHNICAL EVALUATION COMPLETE
 - FEASIBLE TO LICENSE AND TRANSPORT FUEL
 - OVERALL SCHEDULE 24-29 MONTH
 - APPROVAL REQUIRED FROM FRENCH COMPETENT AUTHORITY (FCA), STATE DEPARTMENT, DOT AND NRC - PROJECTED TO TAKE 6 MONTHS
- · CURRENT ACTIVITIES
 - NYPA CONTINUES DISCUSSIONS WITH COGEMA
 - AUTHORIZATION TO PREPARE LICENSE APPLICATION FOR CASK

NYPA DECOMMISSIONING PLAN

- · DRAFT PLAN PREPARED AND IN REVIEW
- · MAJOR ELEMENTS
 - DECON METHOD (EARLY DISMANTLEMENT)
 - SEGMENTATION OF VESSEL
 - COMPLETION IN 1993
- · LILCO INPUTS
 - MUCH OF LILCO PLAN UTILIZED
 - NED REANALYZED ACCIDENT SCENERIOS
- . SUBMITTAL SCHEDULED BY END OF DECEMBER

NRB MEETING 12/13/90

- . NGAD REORGANIZATION
- DECONTAMINATION PROGRAM QUALITY
 ASSURANCE
- · QA PROGRAM REVIEW YEAR END 1990
- . NOA DEPARTMENT OVERVIEW

NQAD REORGANIZATION


NUCLEAR QUALITY ASSURANCE REPORTING:

- · CORPORATE QUALITY ASSURANCE
 - POLICY MATTERS
 - PERSONNEL ADMINISTRATION
 - COORDINATION OF RESOURCES
 - BUDGETARY CONTROL
- VICE PRESIDENT OFFICE OF CORPORATE SERVICES AND VICE PRESIDENT OFFICE OF NUCLEAR
 - DIRECT OPERATIONAL CONTROL
 - DAY-TO-DAY QA PROGRAM ACTIVITIES
- · PRESIDENT:
 - DIRECT COMMUNICATION FOR MATTERS CONCERNING NUCLEAR SAFETY

NOAD REORGANIZATION

- NRB REPORTS DIRECTLY TO VICE PRESIDENT OFFICE OF CORPORATE SERVICES AND VICE PRESIDENT OFFICE OF NUCLEAR
- ISEG REPORTS DIRECTLY TO MANAGER NQAD, SAFETY ENGINEERING AND RELIABILITY DIVISION ELIMINATED
- NDE REPORTS TO MANAGER CORPORATE
 QUALITY ASSURANCE VIA CORPORATE
 QUALITY CONTROL DIVISION MANAGER

ORGANIZATION FOR NUCLEAR QUALITY ASSURANCE




DECONTAMINATION PROGRAM QUALITY ASSURANCE

- . PIPING SYSTEMS AND STRUCTURAL
 - CHARACTERIZATION PRIOR TO DECON WITNESSED BY QC
 - BID SPEC RECEIVED TECHNICAL AND QUALITY ASSURANCE REVIEWS
 - TASK FORCE EVALUATION OF DECONTAMINATION PROCESS
 - TASK FORCE INCLUDES ENGINEERING AND QUALITY ASSURANCE
 - MATERIAL STUDY 6 SYSTEMS/22 DIFFERENT MATERIAL COUPONS
 - INDEPENDENT CONFIRMATORY TESTING
 - PLANT MAINTENANCE AND QUALITY ASSURANCE PERSONNEL TRAINED IN HYDROLAZER OPERATION AND SAFETY
 - MAINTENANCE PERSONNEL HYDROLAZER QUALIFICATION VERIFIED BY QC
 - FINAL SURVEY AFTER DECON WITNESSED BY QC


CA PROGRAM REVIEW YEAR END 1990

- · AUDITS
 - TOTAL AUDITS 16
 - NRB 10
 - NQA 6
 - FINDINGS 22
 - CURRENTLY OPEN 3
- · PROCUREMENT AUDITS
 - TOTAL AUDITS 43
 - NUPIO 34
 - LILOO 7
 - OTHER 2
- · HOTLINE
 - 1990 4
 - 1989 7
- · LDR
 - 1990 TOTAL 124
 - 1989 TOTAL 211
- · CAR
 - 1990 1
 - 1989 2
- · TREND
 - MATERIAL UTILIZATION CAR 90-01 1st Qtr
 - TRAINING QUALIFICATIONS 3rd Qtr

QUALITY HOTLINE PROGRAM




SHOREHAM OPEN LDR'S




NOA DEPARTMENT OVERVIEW

- · STAFFING
- . SICK RECORD
- . TEMPORARY ASSIGNMENTS
- · LIFA/NYPA

NQA MANPOWER CHART



NQA MONTHLY AVERAGE SICK LEAVE



*DOES NOT INCLUDE MATERNITY.
ANNUAL GOAL IS 4 DAYS PER PERSON

Attachment 4

Letter Documenting

Drop-In Visit by

John Leonard, LILCo



UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGIONI

476 ALLENDALE ROAD

KING OF PRUSSIA, PENNSYLVANIA 19408

Docket No.

50-322

Long Island Lighting Company

ATTN:

Mr. John D. Leonard, Jr.

Vice President - Offices of

Corporate Services and Nuclear

Shoreham Nuclear Power Station P. O. Box 618, North Country Road Wading River, New York 11792

Gentlemen:

We appreciate the brief remarks on status and schedules you provided to my staff and me during your drop-in visit at the Region I office of the NRC on September 11, 1990. Enclosed is a summary of our discussion; please content in the promptly if you note any errors in this summary.

Sincerely,

A. Randolph Blough, Chief Reactor Projects Branch No. 2

Mundel 25°C.

Division of Reactor Projects

Enclosure: as stated

cc w/encl:

L. Calone, Plant Manager

J. Wynne, Operations Division Manager

R. Gutmann, Manager, Nuclear Operations Support

R. Kascasak, Managor, Nuclear Engineering

V. Staffieri, General Counsel

W. Maloney, Manager, QA Department

Director, Power Division

State of New York, Department of Law

Shoreham Hearing Service List

Public Document Room (PDR)

Local Public Document Room (LPDR)

Nuclear Safety Information Center (NSIC)

NRC Resident Inspector

State of New York

'acc w/encl:

Fazing I Don A Room (with concurrences)

. Yanamy, DRSS

ad inapp, DRSS

W Hodges, DRS

L. Doerfiein, DRP

B. Norris, DRP

J. Nakoski, DRP

M. Young, OGC

K. Abraham, PAO (2)

J. Caldwell; EDO

S. Weiss, NRR

S. Brown, NRR

C. Mullins, OGC

SHOREHAM SERVICE LIST

Gerald C. Crotty, Esquire Ben Wiles, Esquire Counsel to the Governor Executive Chamber State Capital Albany, New York

Fabian G. Palomino, Esquire Suffolk County Atturney Executive Chamber State Capitol Albany, New York 12224

Mr. Jay Dunkleberger New York State Energy Office Agency Building 2 Empire State Plaza Albany, New York 12223

Energy Research Group, Inc. 400-1 Totten Pond Road Waltham, Massachusetts 02154

W. Taylor Receipt III, Esquire Hunton & Williams Post Office Box 1555 Richmond, Virginia 23212

Stephen Latham, Esquire John F. Shea, Esquire Twomey, Latham & Shea Post Office Box 398 33 West Second Street Riverhead, New York 11901

Jonathan D. Feinberg, Esquire New York State Department of Public Service Three Empire State Plaza Albany, New York 12223 James B. Dougherty, Esquire 3045 Porter Street, N.W. Washington, D.C. 20008

Paul Sabatino, II, Attorney at Law Counsel to Legislature Legislative Building Veteran's Memorial Highway Hauppauge, New York 11786

Honorable Patrick Halpin Suffolk County Executive County Executive/Legislative Bldg. Veteran's Memorial Highway Hauppauge, New York 11788

MHB Technical Associates 1723 Hamilton Avenue, Suite K San Jose, California 95125

Martin Bradley Ashare, Esquire Suffolk County Attorney H. Lee Dennison Building Veteran's Memorial Highway Hauppauge, New York 11788

Karla J. Letsche, Esquire Kirkpatrick, Lockhart, Hill, Christipher and Phillips 1800 M Street, N.W. Suite 900, South Lobby Washington, D.C. 20036-5891

Brookhaven Town Attorney 3233 Route 112 Medford, New York 11763 Ezra I. Bialik, Esquire
Assistant Attorney 'eneral
Environmental Protection Bureau
New York State Department of Law
120 Broadway
New York, New York 10271

Herbert H. Brown, Esquire Lawrence Coe Lanpher, Esquire Kirkpatrick, Lockhart, Hill, Christopher & Phillips 1800 M Street, N.W. Suite 900, South Lobby Washington, D.C. 20036

Richard M. Kessel Chairman and Executive Director New York State Consumer Protection Board Room 1725 250 Broadway New York, New York 10007

Alan S. Rosenthal, Esquire Chairman, Atomic Safety & Licensing Appeal Panel U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Howard A. Wilbur, Esquire Atomic Safety & Licensing Appeal Panel U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Joseph I. Lieberman, Attorney General State of Connecticut 30 Trinity Street Hartford, Connecticut D6106 Francis J. Gluchowski, Esquire Assistant Town Attorney Town of Brookhaven Department of Law 3233 Route 112 Medford, New York 11763

Adjudicatory File
Atomic Safety and Licensing Board
Panel Docket
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Department of Public Service Director, Power Division Three Empire State Plaza Albany, New York 12223

Gary J. Edles, Esquire Atomic Safety & Licensing Appeal Panel U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Robert Abrams, Esquire Peter Bienstock, Esquire Department of Law State of New York 120 Broadway New York, New York 10271

ENCLOSURE

Drop-in Visit from LILCO Vice-President

On September 11, 1990, Mr. John D. Leonard, Jr., (Vice-President, Offices of Corporate Services and Nuclear) from LILCo visited the NRC Region I offices on short notice. He met with Mr. A. R. Blough, Reactor Projects Branch Chief, Mr. L. T. Doerflein, Reactor Projects Section Chief, and Mr. B. S. Norris, Projects Inspector (Shoreham), from 9:00 a.m. until 9:45 a.m. Mr. Leonard had requested the visit to ensure that the region is kept current with respect to the activities at Shoreham. Mr. Leonard discussed status of the following areas:

- License transfer request LILCo's operating costs will be reduced once the license is transferred to the Long Island Power Authority.
- * Financial plan for decommissioning LILCo is considering revising their previous submittal.
- Decontamination of plant systems LILCo has decided to do a pilot decontamination of the Reactor Water Clean-Up (RWCU) system using the "regenerative decontamination" method.
- Quality Assurance (QA) LILCo is considering requesting a change to the USAR which will allow the Corporate QA and site Nuclear QA groups to be combined.
- * NUMARC Mr. Leonard provided to the NRC Region I, copies of two NUMARC letters that had been sent to NRC Headquarters. The subjects of the letters are: (1) Nuclear Plant Closure Activities that may be Prepared in Advance of Approved Decommissioning Plan (April 3, 1990), and (2) National Environmental Policy Act (NEPA) as it relates to decommissioning (April 6, 1990).
- Shipping of components LILCo is pursuing options for shipping of the IRMs and SRMs, the control rod blades, and the fuel support pieces.
- * EP News Center the Emergency Plan News Center is being returned to Haupauge to be closer to the site.

No technical, licensing or unresolved items were discussed substantively.