

50-267-  
S

X



**Public Service Company of Colorado**

P. O. Box 361, Platteville, Colorado 80651

October 24, 1978  
Fort St. Vrain  
Unit No. 1  
P-78171

Mr. Karl V. Seyfrit, Director  
Nuclear Regulatory Commission  
Region IV  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76012

REF: Facility Operating License  
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/78-31/03-L-0, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/78-31/03-L-0, Final.

Very truly yours,

*Don Warembourg*  
Don Warembourg  
Nuclear Production Manager

DW/alk

cc: Director, Office of Management Information  
and Program Control

7810270228 S

D<sup>002</sup> S/11