



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

March 2, 1983

33 MAR 8 AIO: 20

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - Fire Barriers
Broken to Route Cables
LER 82-166/99 X-1
AECM-83/0138

This letter submits an update to a previous report submitted on January 7, 1983. The event for which the report was submitted occurred on December 2, 1982, when fire barriers were broken in the Control Building Computer Room, Control Room and Upper Cable Spreading Room to route cables under a maintenance work authorization. The event was reported in a Special Report pursuant to Technical Specification 3.7.7.a.

All corrective action for this event is now complete. Attached is LER 82-166/99 X-1, which is a final report.

Yours truly,

Joseph Richard
FOR J.P. McLaughly JR.

JPM:sap
Attachment

cc: Mr. N. L. Stampley (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

IE 22