SEP 17 1980

Docket Nos. 30-06106 30-12704 30-13168

> Hamilton Watch Company ATTN: Mr. P. Karporizis 901 Wheatland Avenue Lancaster, Pennsylvania 17604

Gentlemen: .

Subject: Inspection 80-01

This refers to the routine inspection conducted by Ms. J. McGinness and Ms. M. Campbell of this office on August 28, 1980, of activities authorized by NRC License Nos. 37-3572-02E, 37-3572-06 and 37-3572-07E and to the discussions of our findings held by Ms. McGinness with yourself at the conclusion of the inspection.

The inspection was an examination of activities conducted under your licenses as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your licenses. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

In addition, our inspectors took smear samples in your room where watches containing gaseous tritium are assembled and the room adjacent to it, which were analyzed in our Regional Office Laboratory in King of Prussia, Pennsylvania. The basic purpose of these independent measurements is to evaluate removable contamination in your use and storage areas. As Ms. McGinness informed Mr. S. Cliff in a telephone conversation on September 8, 1980, the results of our analysis showed detectable levels of activity on your workbench surfaces, drop test box, tritium storage cabinet and floor outside the gaseous tritium watch assembly room. These levels were not in excess of generally acceptable guidelines for removable contamination.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter will be placed in the Public Document Room.

			nl. I		
		C	801023	10236×4	HIJY
OFFICE M	BH QMS	LAF 8115	FERMS		
IRNA	McGinness/mjd	Campbell	Kinneman		
DATE	9/15/80	9.16.62	9-16-82		

Hamilton Watch Company

SEP 1 7 1980

2

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

John D. Kinneman, Chief Materials Radiological Protection Section

bcc:

IE Mail & Files (For Appropriate Distribution) Central Files Public Document Room (PDR) Nuclear Safety Information Center (NSIC) REG:I Reading Room Commonwealth of Pennsylvania License Fee Management Branch

OFFICE 🍉		*****		a a canada da sa	
SURNAME 🍉					
DATE .		a and a second		a contra a c	<u>alangina ang </u>
NRC Form 318	(8 (4 79) NRCM 0240	. U. S. GOVERNMENT REINTI	NG OFFICE 1815-181-404		