

TO: Referring Physician Dr. []

HA report copy

NRC Regional Office
Office of Inspection and Enforcement

Also send copy to:
U.S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, D.C. 20555

30-13993

REPORT OF DIAGNOSTIC MISADMINISTRATION

Date of report 2-4-81 Date of Incident 2-4-81

Licensee Shelbygan Memorial Hospital Number 48-18654-01

Address 2629 North 7th Street

City, State Shelbygan, Wisconsin 53081

Referring Physician Dr. []

Signature _____

Description of event The patient came in for a thyroid scan. The doctor's office was called to confirm the order which his nurse did. After the injection, it was discovered the doctor wanted a thyroid ultrasound.

Effect on patient No ill effects of the patient were observed. Five mCi of Technetium was used.

Preventive action When a thyroid scan is ordered, determine if the doctor wants a nuclear medicine thyroid scan or a thyroid ultrasound.

This report is to be sent within ten (10) days after the end of calendar quarter in which the incident occurred.

The Medical Isotope Committee and the licensee (administration) has been informed of this incident.

Submitted by:

XA Copy Has Been Sent to PDR

8104070367 XA

Robert J. Scott

Radiation Safety Officer

1