			U.S. NUCLEAR REGU	U.S. NUCLEAR REGULATORY COMMISSION	
10 CFR 2.201 SAFETY INSPECTION		J. B. O. June	1 B-O Juniar		
			PUBLIC	Page 1 of /	
1. LICENSEE		2. REGIONAL OFFICE			
Richardson Electre		REGIO	DN III		
40 03 2.67 Kershingen field US NUCLEAR REGULATORY COMMISSION					
Richarden Electronics, Ltd REGION III 40 W 267 Kershingen Rid La Fox, IL 60147 GLEN ELLYN IL 60137					
3. DOCKET NUMBER(S)			5. DATE OF INSPECTION		
070-04181 12-09745-02E April 21, 1994				294	
1030-04181 12-01140-40C					
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear					
Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as					
follows:					
1. Within the scope of this inspection, no violations were observed.					
 The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time. 					
 During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a NOTICE OF VIOLATION, which is required to be posted in accordance with 10 CFR 19.11. 					
A			was not properly	posted to	
indicate the presence of a		. 10 CFR 20.203(. 10 CFR 20.203(b),(c),(d),(e) or 34.42.		
В.	B		of sealed sources	of sealed sources were not	
performed at the proper frequencies. 10 CFR or License Condition Number					
C. Records of					
10 CFR or License Condition Number					
D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.					
E. Reports or notification of					
10 CFR	10 CFR or License Condition Number				
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.					
SIGNATURE - LIGENSEE 018	DATE	SIGNATURE - NRC INS	PECTOR	DATE	
9405270036 940421 PDR ADOCK 03004181 C PDR		Early RI	Matan	4/21/94	
F MR	a destination of the second	talini u shakitataki kashesi make		A second s	