

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205 March 7, 1983

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-13 File 0260/L-835.0 Update Report - Inoperable Fire Rated Assembly LER 82-122/99 X-1 AECM-83/0154

This letter submits an update to a previous report submitted on December 13, 1982. The event for which the report was submitted occurred on November 4, 1982, when it was discovered that the cover to the HVAC chase in the Control Building Lower Cable Spreading Room had been removed. The report was submitted as a Special Report pursuant to Technical Specification 3.7.7.a.

All corrective action is complete. Attached is LER 82-122/99 X-1, which is a final report.

Yours truly,

LIDA-for J.P. H Engly

JPM:sap Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Tear