

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205 March 8, 1983

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

250

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Update Report - Fire Barriers Opened to Reroute a Cable

LER 82-178/99 X-1 AECM-83/0157

This letter submits an update to a previous report submitted on January 24, 1983. The event for which the report was submitted occurred on December 18, 1982, when several fire barriers in the Control Room floor were opened to reroute a cable through the floor. A Limiting Condition of Operation was initiated and an hourly fire watch was established in accordance with Technical Specification 3.7.7.

All corrective action is complete. Attached is LER 82-178/99 X-1, which is a final report.

Yours truly,

for J. P. M. Engly

JPM: sap Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555