

MAR 4 1983

APPENDIX A

NOTICE OF VIOLATION

Naval Regional Medical Center  
Philadelphia, Pennsylvania 19145

Docket No. 30-03010  
License No. 37-01848-01

As a result of the inspection conducted on February 2, 1983, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

Condition 17 of License No. 37-01848-01 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in application received August 18, 1982.

1. Block 10 of this application requires that dose calibrators be calibrated in accordance with procedures contained in Appendix D, Section 2, of Regulatory Guide 10.8.

Item A.1 of Appendix D, Section 2, requires that dose calibrator linearity be determined at installation and quarterly thereafter.

Contrary to the above, as of February 2, 1983, dose calibrator linearity had not been determined since October 1972, a period of more than a calendar quarter.

This is a Severity Level IV Violation. (Supplement VI)

2. Block 14 of this application requires that packages containing radioactive material be opened in accordance with the procedures in Appendix F of Regulatory Guide 10.8.

Item 6 of Appendix F requires that the external surface of the final source container be wiped to check for contamination and the results recorded.

Contrary to the above, as of February 2, 1983, records of the required wipes of the final source containers had not been maintained.

This is a Severity Level V violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, the Naval Regional Medical Center, Philadelphia, Pennsylvania is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including; (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8303160591 830304  
NMS LIC30  
37-01848-01 PDR