

1100 Seminary Street
Rockford, Illinois 61105
(815) 987-2665
Telex 257-479



February 28, 1983

United States Nuclear Regulatory Commission
Region 111
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attn: Mr. D. G. Wiedeman
Chief Material Radiation Protection
Section 1

Dear Mr. Wiedeman:


In reply to your request following our inspection tour on January 4, 1983 and subsequent letter received January 12, 1983, I have done the following:

- 1) Have posted Part 19, Part 20. Also, on that notice in the designated area, I have shown the location of our license, license conditions document incorporated into the license, license amendments and operation instructions.
- 2) Have performed required test on sealed source, under the directions of qualified personnel, and sent results to ICN Laboratories for analysis. I am waiting for the results and will forward them as soon as received.
- 3) I believe we are now in full compliance.

I would like to personally thank you for your efforts. Especially for taking the time to instruct us.

Sincerely yours,

BEHR ALLOYS COMPANY


Kevin Jacobs
Radiation Protection Officer

KJ:JMD