

Midland Project: PO Box 1963, Midland, MI 48640 + (517) 631-8650

March 3, 1983

FRINCIPAL STAFF
IRA ENF
ID/RA ISCS V 0/10/13
A/RA PAO
DERP SLO
DRMA RO
DRMSP
DE
ML
OL FILEIN/W

Donald B Miller, Jr Site Manager Midland Project

Mr. W. D. Shafer, Chief Midland Project Section U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND PROJECT GWO 7020 CLARIFICATION TO THE WORK ACTIVITY LIST File: 0485.16 UFI: 07070(S) Serial: CSC-6586

The purpose of this letter is to document discussions held with Dr. Landsman on March 2, 1983. Our R. M. Wheeler proposed deleting from the Work Activity List the activity described as "Monitor and Adjust Pier Jacks after Load Transfer". It was explained that this activity was already covered under the activity described as "Install and Load Pier".

After reviewing the activity, Dr. Landsman concurred with deleting the activity entitled "Monitor and Adjust Pier Jacks after Load Transfer" from the Work Activity List.

INEMES

D. B. Miller, Jr.

Site Manager

DBM/RMW/lrb