

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

February 22, 1982

82 FEB 25 P 1: 53

USNRC REGION II
ATLANTA, GEORGIA

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


YELLOW CREEK NUCLEAR PLANT UNITS 1 AND 2 - QUALITY ASSURANCE AUDIT M80-7
DEFICIENCIES 2, 3, 5, AND 14 - SIXTH INTERIM REPORT

The deficiencies 2, 3, and 5 were initially reported to NRC-OIE Inspector M. Thomas on September 23, 1980, in accordance with 10 CFR 50.55(e). A first interim report was submitted on October 23, 1980. After that time, construction quality assurance audit deficiency 14 was also considered to be a significant condition adverse to quality. This was followed by our interim reports dated November 25, 1980, March 20, September 24, and December 2, 1981. TVA is still in the process of reviewing the subject deficiencies. A more detailed report of this review will be provided in our next report which we expect to submit by June 24, 1982.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555



OFFICIAL COPY
JE27510