TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

February 23, 1982

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303 82 FFR 25 Pl. 50

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE REPORT BFRO-50-260/82006

The enclosed report provides details concerning a reactor low-water level switch which was found out of tolerance. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 6.7.2.b(1).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

& H. J. Green

Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

9 RECEIVED
MAR 05 1982

WAR 05 1982

WE WILLIAM RESIDENT TOUR STATE OF THE PROPERTY OF THE PRO